ASS. REC. BY: Taufik | REF: CS3/AIG 21004568/T1+T3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 4843613936SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 463K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP' PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA1922Z Yr Regn: 2018, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Grace c.c 1496

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 36045 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GM6110054 6

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : NIl / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	mm
D.O.A.		D.O.I.	4/4/21

Survey held at Alpha Motor

Des. of Damages: F/O / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SUBMIT DAR REPORT, 4DAYS

Date/Time, File Pass to? ☐ : Prell. Report

1) _____ ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:

Transportation: $ + RS. $

Photos

Others

TOTAL

Report Format : _____

Lump Sum / L.B.I: (% _____)