ASS. REC. BY:	CS/ICS21004580/Ktf3
lenneth A	ASSIGNMENT
From: Date:	Veh No: JKS 6P 74 UYr Regn: 04, 15
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Ledys ES 250 c.c 2894
at Workshop m/s Alan's.	Colour M. Cray AC: Insured / Std / NI / NA
of	Sp.Reading 606 f 3 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: 374BJIGG602077814
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STDA/Rim or
	Tyre Size: F: 215/55R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO NOKO or
Bal, or Market Value: 2 Pok	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm R/Bal. Z mm
GIA / PR Seen: Consistent?: Yes or No	UBal. / mm UBal. 7 mm
Est. Repairs: 05 days Res.: Yes or No	D.O.A. 8/4/21 D.O.I. 12/4/202
Lum Sum: 1.B-1 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
DART BY DART \$2105 90	FDAVE
PART BY PART \$3195.80	J, SDAYS
(RED:14; 4%)	
Dato/Time, File Pass to? Prell. Report	Days Of Repair: 5
()	Pariments and
Duta/Time, File Return to?	
Add Fee:	: Site Insp (\$) S.ES SI
•)S+RSSI
eport Format :	Interview (\$) Fartos
ump Sum / I.B.I: (\$ 3195.8	Tech Invs (\$): Others
	Weekend (\$
	1074
	TOTAL