

ASSIGNED BY: *ad*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *LCR*

of _____

Insured: _____

Policy No. **DMCVSNW00069152000**

Claims No. **SNM21D201931/C02/LEWLC**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value *\$56K*

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est Repairs *10* days Res. Yes or No

Lum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SUH4123T* Yr Regn: *02 Nov 2016*

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *1.5 Hybrid*

Make: *Handa shuttle* cc *1490*

Colour: *Silver* A/C: Insured / Std / NI / NA

Sp Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *6P7643301*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modj: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *185/60R15*

R: *7*

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Road march*

Front _____ Rear _____

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A. _____ D.O.I. *12-04-21*

Survey held at *W/S*

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or *4pm*

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Rebate: 3/050

**Finalize COR \$17950 before GST @ 10 days.
red:20991.28;53%**

38941.28

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: **10**
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Insp. (\$)
 : [unclear] (\$)

Survey Fee: _____
Transportation: _____
_____ \$ + PS _____ \$
Flares _____
Other _____
Total _____

LCRF PTE LTD
 CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd
 Date 8/4/2021
 Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH4123T
 CHASSIS NO : GP71043301
 MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT
 DATE OF ACCIDENT : 01/04/2021
 YOUR INSURED VEHICLE NUMBER : GBH101B
 MILEAGE: 110875

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front windscreen glass / <i>CRD</i>	1PC	\$2,300.00	\$2,300.00
2	Front bonnet / <i>one</i>	1PC	\$1,380.00	\$1,380.00
3	Front bonnet LH hinge / <i>SBT</i>	1PC	\$60.00	\$60.00
4	Front bonnet RH hinge / <i>SBT</i>	1PC	\$60.00	\$60.00
5	Front bonnet insulator / <i>De</i>	1PC	\$165.00	\$165.00
6	Front bonnet lock assy / <i>SBT</i>	1PC	\$195.00	\$195.00
7	Front bonnet lock catch / <i>SBT</i>	1PC	\$150.00	\$150.00
8	Front bonnet seal / <i>two</i>	1PC	\$75.00	\$75.00
9	F/L fender / <i>one</i>	1PC	\$1,100.00	\$1,100.00
10	F/R fender / <i>X repair</i>	1PC	\$1,100.00	\$1,100.00
11	F/L fender inner liner / <i>1 TW</i>	1PC	\$240.00	\$240.00
12	F/R fender inner liner / <i>1 TW</i>	1PC	\$240.00	\$240.00
13	F/ fender Hybrid emblem / <i>1 ac</i>	1PC	\$86.80	\$86.80
14	F/R fender Hybrid emblem / <i>1 ac</i>	1PC	\$86.80	\$86.80
15	Front support panel top cover / <i>De</i>	1PC	\$250.00	\$250.00
16	Front support panel	1PC	\$1,050.00	\$1,050.00
17	Radiator grille center moulding / <i>Dis.</i>	1PC	\$390.00	\$390.00
18	Radiator grille base / <i>Dis.</i>	1PC	\$325.00	\$325.00
19	Radiator grille lower moulding / <i>Dis.</i>	1PC	\$330.00	\$330.00
20	Radiator grille emblem / <i>Dis.</i>	1PC	\$48.00	\$48.00
21	F/L headlamp / <i>Dis.</i>	1PC	\$1,215.00	\$1,215.00
22	F/R headlamp / <i>Dis.</i>	1PC	\$1,215.00	\$1,215.00
23	F/L headlamp lower bracket / <i>Dis.</i>	1PC	\$115.00	\$115.00
24	F/R headlamp lower bracket / <i>Dis.</i>	1PC	\$115.00	\$115.00
25	Front bumper / <i>Dis.</i>	1PC	\$1,350.00	\$1,350.00
26	Front bumper reinforcement / <i>BT</i>	1PC	\$660.00	\$660.00
27	Front bumper RH tow cover / <i>AT</i>	1PC	\$54.00	\$54.00
28	Front bumper RH side retainer / <i>1 cont.</i>	1PC	\$21.00	\$21.00
29	Front bumper LH side retainer / <i>1 cont.</i>	1PC	\$21.00	\$21.00

30	Front bumper RH fog lamp cover	✓ Sht	1PC	\$150.00	\$150.00
31	Front bumper LH fog lamp cover	✓ Sht	1PC	\$150.00	\$150.00
32	Front bumper lower grille	✓ PIS	1PC	\$294.00	\$294.00
33	Front windscreen washer tank	✓ RE	1PC	\$250.00	\$250.00
34	Front RH wheel house upper member	?	1PC	\$480.00	\$480.00
35	Front RH wheel house lower extension	?	1PC	\$480.00	\$480.00
36	Radiator assy	✓ SBT	1PC	\$1,800.00	\$1,800.00
37	Air con condenser	✓ SBT	1PC	\$900.00	\$900.00
38	Radiator fan motor	?	1PC	\$850.00	\$850.00
39	Aircon condenser motor	?	1PC	\$700.00	\$700.00
40	Radiator shroud	?	1PC	\$250.00	\$250.00
41	Inlet manifold	?	1PC	\$480.00	\$480.00
42	Driver air bag	✓	1PC	\$3,000.00	\$3,000.00
43	Passenger air bag	✓	1PC	\$3,000.00	\$3,000.00
44	Dashboard	✓	1PC	\$2,000.00	\$2,000.00
45	SRS ECU	✓	1PC	\$2,030.00	\$2,030.00
46	F/R crash sensor	✓	1PC	\$200.00	\$200.00
47	F/L crash sensor	✓	1PC	\$200.00	\$200.00
48	F/L safety belt	✓	1PC	\$750.00	\$750.00
49	F/R safety belt	✓	1PC	\$750.00	\$750.00
50	F/L safety belt buckle	X SNN	1PC	\$120.00	\$120.00
51	F/R safety belt buckle	X SNN	1PC	\$120.00	\$120.00
52	Steering reel coil	?	1PC	\$400.00	\$400.00
				LIST TOTAL S\$:	\$33,751.60
				20.00% DISCOUNT S\$:	\$6,750.32
					\$27,001.28

SPECIAL NETT

1	Front windscreen sealant	✓ MCL	1 SET	\$120.00	50
2	Body sealant	X NN	1 SET	\$300.00	
3	Front bumper clips	✓ MCL	1 SET	\$120.00	30
4	Front number plate	✓ SBT	1 SET	\$80.00	40
				Special Nett Total S\$:	\$620.00

LABOUR CHARGES

1	TO REMOVE FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, F/R WHEEL HOUSING UPPER MEMBER AND F/R CHASSIS OUTER MEMBER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS. ALSO INCDE CUTTING AND WELDING OF DAMAGED PARTS	250	\$2,500.00	1750.
2	TO RESPRAY FRONT BONNET, BOTH FRONT FENDERS, SUPPORT PANEL, F/R WHEELHOUSE AND FRONT BUMPER(INNER/OUTER)	220	\$1,800.00	1320
3	TO REMOVE & INSTALL FRONT WINDSCREEN		\$160.00	120.
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		\$80.00	60.
5	TO ACTIVATE AND DEACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS		\$300.00	200.

6	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	\$300.00	120.	
	TO LABOUR CHARGE FOR REMOVING AND			
7	INSTALLING ENGINE ASSY OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	\$500.00	?	
8	TOWING FEE	\$50.00	(LOP).	
	TO LABOUR CHARGE FOR RREMOVING AIR CON SYSTEM OUT TO FACILITATE			
	REPLACEMENT OF DAMAGED PARTS AND INCUDE VACUUMING OF AIR CON GAS	\$300.00	120.	
	TO LABOUR CHARGE FOR REMOVING AND			
9	INSATTING DASHBOARD TO FACILITATE REPLACEMENT OF SRS AIR BAG	\$500.00	200	
10	TO CONFIGURE AND REPROGRAM SRS AIR BAG ECU BACK TO FACTORY SPECIFICATION	\$500.00	200.	
	TO REMOVE AND INSTALL FRONT ENGINE			
11	ASSY OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	\$500.00	X	
	TO LABOUR CAHRGE FOR REMOVING AIR CON SYSTEM OUT TO			
12	FACILITATEREPLACEMENT OF DAMAGED AIR CON PARTS. ALSO INCUDE VACUUMING AND RENEWING AIR CON GAS	\$380.00	X	} NN
13	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS	\$160.00	X	
	LABOUR TOTAL S\$:	\$8,030.00		
	TOTAL S\$:	\$35,031.28		
	7% GST	\$2,452.19		
	GRAND TOTAL S\$:	<u>\$37,483.47</u>		

10 Days.

Impson Repair

After repair photos.

Geo Qial - 82880282

12/4/2021.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/04/2021 12:04 (SGT)
Date of Accident	01/04/2021 23:45 (SGT)
Exact Location of Accident	Blk 216B, Singapore
Additional Location Information	CROSS JUNCTION OF CORPORATION ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH4123T
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Company Reg No	2XXXXX621K
Email Address	rentals@lioncityrentals.com.sg
Mobile Phone No	(Phone) +65-62525525
Alternative Phone No	(Office) +65-62525525

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	21-MM000075-R00
Cover Note Number	-

DRIVER

Name of Driver	[REDACTED]
NRIC No	[REDACTED]

Date Of Birth	[REDACTED]
Occupation	[REDACTED]
Date Of Driving Pass	[REDACTED]
Driving experience	[REDACTED] YEARS AND 1 MONTH
Gender	[REDACTED]
Mobile Number	[REDACTED] 85-63398113
Alt. Phone Number	-
Email Address	[REDACTED]
Address	[REDACTED] BUKIT BATOK SINGAPORE
Address complement	-
Postcode	[REDACTED]
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Batok Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18006659999
Alt. Police Station Phone No	(Fax) +65-64252661
Police Station Address	21 Bukit Batok East Ave 4 Singapore 659840
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH101B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Please refer to police Report

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by: _____



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/04/2021 19:22	Vide Report No.:	Station Diary No.: 68
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: MOHAMMAD BARMAD BIN MOHAMMAD SHARIFF		Address: [REDACTED]	
ID Type / ID No.: NRIC NO / 7618737A		Contact No.: Home/Office: Mobile: [REDACTED]	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: [REDACTED]	Date of Birth: 08/07/1978	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: PRIVATE HIRE DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/04/2021 23:45	Type of Location: X-Junction
Location: CORPORATION ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH101B	Van	MERCEDES BENZ	VITO 114 CDI PANEL VAN LONG AT ABS 5DR	Silver		1
SLH4123T	Car	HONDA	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2W	Silver	Seriously Damaged	0



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	Unknown *	ID No.	NIL
Related Vehicle	GBH101B (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	[REDACTED]	ID No.	[REDACTED]
Related Vehicle	[REDACTED]	Contact No.	[REDACTED]
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	02/04/2021	Date Discharge	05/04/2021
No. of Days granted Medical Leave	17	Degree of Injury	Slight

Brief Details.

On 05/04/2021 at about 2340hrs, I was driving my vehicle bearing the registration plate SLH4123T along Corporation road towards Jurong Port Road. At the material time, I was travelling towards Penjuru, performing a Grabfood delivery. While I was approaching the traffic light cross junction along Corporation Road, as the traffic light is still green, I had my right of way thus I continued driving straight. However out of a sudden, at the opposite direction, a van bearing the registration plate GBH101B turned right. I tried to brake however it was too late and the frontal side of my vehicle collided into the body of the van.

After the collision, the driver of the said van helped me out of the vehicle and at the point of time I was still conscious however was in a lot of pain. I was subsequently being conveyed to National University of Hospital by ambulance. Traffic Police arrived at scene as well. I was being treated at the hospital on 02/04/2021 and then discharged on 05/04/2021 with 17 days of MC. I sustained bruises on my left shoulder, right leg and on the neck area, as well as lacerations on both of my arms.

The frontal part of my vehicle was seriously damaged. There is a working in car camera Inside my vehicle which is with my car rental company now as my vehicle was being towed on the day of incident. IO Adelina, HP: 97556507 from Traffic Police had contacted me when I discharged to ask me to lodge a police report.



**SINGAPORE
POLICE FORCE**



T/20210405/2113

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 4

Report No: T/20210405/2113

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20210405/2113

4 of 4

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20210405/2113

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J / Sgt 2 YEO YULIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/04/2021 19:22
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case:
Authentication Stamp NP168	 SIGNATURE

