SG0G21490003 / Go Ahead Singapore Pte Ltd ENTRY DATE & TIME: 12/04/2021 09:52 (SGT) SUBMITTED BY: Chan Weijie VERSION: 1 (12/04/2021 09:52 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 12/04/2021 09:52 (SGT) Date of Accident 07/04/2021 09:12 (SGT) Exact Location of Accident Punggol Central & Punggol Way, Singapore Additional Location Information Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SG5438B

#### INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner GO AHEAD SINGAPORE PTE LTD Company Reg No **XXXXXXXXXX** 900C **Email Address** NO ROCE CONCORDED ROCE OR OTHER PROPERTY OF THE PROPERTY OF TH Mobile Phone No (Phone) +65**)3333333333333333** Alternative Phone No 

### VEHICLE PARTICULARS

Manufacturer Volvo Model B9tl Variant Exact purpose for which vehicle was being used at time of **Employment** accident Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only Vehicle Category Bus Transmission Auto CC 9400

### **INSURANCE COMPANY**

Name of Insurance Company MS First Capital Insurance Ltd Type of Coverage Comprehensive Fleet Policy Policy Number D-19094111MFBP Cover Note Number

## DRIVER

Name of Driver Lee Keim Fee Work Permit No 

Date Of Birth 18/09/1983 Occupation Outdoor Date Of Driving Pass 23/01/2015 Driving experience 6 YEARS AND 3 MONTHS Gender Mobile Number (Phone) +65x8x8xxxxx Alt. Phone Number Email Address Address XX89404XXX9900000000XXX Address complement Postcode X8X2X0X9400X Is the driver the policyholder? No If No. Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο **DETAILS OF POLICE ACTION** Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT BC Lee was driving service 43 [SG5438B] on the above-mentioned date & time. Based on CCTV footage, he had stopped behind a stationary white BMW [SMJ4647B]. While waiting to exit the slip road, he looked to his right side for traffic on the main road with his footbrake on. SMJ4647B subsequently moved off but stopped again to give way to a blue Mitsubishi Attrage [SME3420X] going straight. After ensuring that there was no oncoming traffic, BC Lee released his footbrake to move off without noticing that the SMJ4647B had come to a stop. BC Lee was unable to brake in time as he was following too closely behind SMJ4647B, resulting in a head to rear collision where the front bumper of SG5438B collided into the rear bumper of SMJ4647B. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

DIFFERENT FORMAT

Vehicle Registration NumberSMJ4647BVehicle ManufacturerBMWVehicle Model523iVehicle Variant-Vehicle ColourWhite

Reasons for not uploading a video of the accident

Was there any audio recorded?

Vehicle Category	Private car
Name of Driver	_
Contact Number	_
Address	_
Address complement	_
Postcode	_
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_





