



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP21004649/Uqf3e2
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date:	01/06/2021
ON BEHALF OF H & R LEASING		Code:	TP149
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SLC 1207G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/04/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11109950	Colour	BLUE
Odometer	128089 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R19	LANDSAIL	5 mm
L/H Front Tyre	245/45 R19	LANDSAIL	5 mm
R/H Rear Tyre	245/45 R19	LANDSAIL	5 mm
L/H Rear Tyre	245/45 R19	LANDSAIL	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/04/2021	Inspection Date	13/04/2021
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	