



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004665/Kvf3n2	
			Date: 08/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 4798E		Veh. Inspected	SGX 1530X
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2101125/THE		Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG		Assign Date	13/04/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)		c.c	1794
Engine No.	HIDDEN		Year of Reg.	2007
Chassis No.	ZNE100364297		Colour	METALLIC GREY
Odometer	188101 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		205/55 R17	KAPSEN	8 mm
L/H Front Tyre		205/55 R17	KAPSEN	8 mm
R/H Rear Tyre		205/55 R17	KAPSEN	8 mm
L/H Rear Tyre		205/55 R17	KAPSEN	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2021		Inspection Date	14/04/2021
Survey held at	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	