



Claim	S1M037TZ
Reference	CS/ASM21004692/T1vce2
Loss Date	10 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	13 Apr 2021 9:17:38 AM
Request Date	13 April 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SLZ4401X

Vehicle
Registration #

Make

TPVD

Model

MERCEDES

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2105471.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2021
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	4 August 2021

FAQ

English (SG) ▾

Elaine Kuan ▾

SUBTYPE

AUTHOR

DATE
UPLOADED

Home

Service Requests

...

ts & Statement

Survey Report

LKK AUTO CONSULTANTS PTE LTD (TP)

4 August 2021

SLZ 4401X IA.pdf.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

29 July 2021

LKKPhotosIn4 res 1.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS PTE LTD (TP)

29 July 2021

LKKPhotosIn4.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS PTE LTD (TP)

29 July 2021

LKKPhotosIn4_compressed.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS PTE LTD (TP)

29 July 2021

SLZ4401X TP GIA.pdf.pdf

Reports & Statement

GIA Report

KUMAR Shailendra

13 April 2021

PRI TP EMAIL FROM SOLICITOR.msg.msg

Letters and Correspondence

Solicitor / Advocate

KUMAR Shailendra

13 April 2021

FAQ English (SG) ▼ Elaine Kuan ▼			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	s and correspondence	Third Party	KUMAR Shailendra	13 April 2021