

Section A - Accident Details

Registration Number	SHB616T
Case Reference Number	TAX/04/21/2014
Registration Date	5/1/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ROY PANG TENG CHOON
Type of Accident	Head To Side
Accident Date and Time	7/4/2021 8:07 AM
Accident Reported Date and Time	7/4/2021 11:58 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110392
Special Instruction to ARC, if any	FRONT RIGHT SIDE
Prepared Date and Time	7/4/2021 4:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$976.00	\$550.00
Total Spray Cost	\$2,034.00	\$700.00
Total Spare Part Cost	\$8,605.69	\$1,490.43
Total Other Cost	\$628.44	\$168.44
TOTAL COST	\$12,244.13	\$2,908.87
Lump Sum Total	\$12,250.00	\$2,900.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	13/04/2021 11:38 AM	13/04/2021 11:08 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0367	Invoice Number	
Quotation Date	22.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION RH	\$676.00	\$400.00
TO REPAIR FRONT SUPPORT PANEL	\$300.00	\$150.00
Total Labour	\$976.00	\$550.00 / Supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$2,034.00	\$700.00 / Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
Total Other Costs	\$628.44	\$168.44 / Nec

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/04/2021

User ID : PohSuan

82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given	X
53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X
53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair	X
53420-47070	HOOD HINRE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X
81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	X
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
16533-28051	SUPPORT RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X
17750-37010	INLET ASSY, AIR	0.00	\$232.50	0.00	\$0.00	Replace	Not Given	X
17700-38252	AIR CLEANER ASSY	0.00	\$929.90	0.00	\$0.00	Replace	Not Given	X
53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X
53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
53701-47050	FENDER APRON SUB FRT/RH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X
42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
Total			\$13,595.85		\$1,863.04			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1863.04

-20%

1490.41
+ 550.00
+ 868.44
2908.85

45 \$2900/-
4 days

SHB 616T

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAXI 04/21/2014	Date of Collection	9/4/21
Vehicle No	SHB 6167	Date of Request	9/4/21
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	1 DAY. /

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	0606,07,08,09	To Repair Support Panel Assy		\$ 300.00 150
2		To Respray Support Panel Assy		\$ 180.00 100
3				
4				
5				
6				
7				
8				

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff