



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21004720/R1uf3e2 Date: 28/06/2021 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SG 1047Y	Veh. Inspected	JSH 1804
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/02/21/1022	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	14/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PMYUG0420H0103017	Colour	MULTI COLOUR
Odometer	76201 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	3 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	13/02/2021	Inspection Date	14/04/2021
Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	