

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21004723/Bqce2	
	8 SHENTON WAY TOWERSINGAPOR		Date:	25/05/2021		
	ATTN: ANG RICHA	ARD		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 4494R	Veh. Inspected	k	SLQ 75C	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M037Z7	Excess (\$)		0.00	
	Assign From	ANG RICHARD	Assign Date		14/04/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA C-HR	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	ZYX1020519ZYX102051967	Colour		WHITE	
	Odometer	69297 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	YOKOHAMA		6 mm	
	L/H Front Tyre	225/50 R18	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/50 R18	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/50 R18	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	. General Information					
	Accident Date	13/04/2021	Inspect Date /	Time	14/04/2021 (01:57 PM)	
	Survey held at HARMONY MOTOR (AMK) PTE LTD					
	BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT SINGAPORE 568047					
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21004723/Bqce2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser