

COMFORT DELGRO ENGINEERING PTE LTD

Date: 14.04.2021

REPAIR ESTIMATE

Time: 13:40:07

Page: 1/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

Atg Asia - CP/P)
 LKK - Steve

JOB NO : 305463644
 REGN NO : SHA1972M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 01.02.2019
 DATE/TIME IN : 14.04.2021 10:55
 ACCIDENT DATE : 10.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	FRT BUMPER	1	430.90	20.00	344.72	/	BR
0002 04-01-0104-2361-G	FRT BUMPER CTR UPR MOULDING	1	368.50	20.00	294.80	/	CHT
0003 04-01-0104-2915-G	HEADLAMP RH	1	1,995.65	20.00	1,596.52	/	CHT
0004 04-01-0104-3813-G	FRT FENDER BLUE-DRIVE RH	1	26.60	20.00	21.28	/	PR
						SUB-TOTAL : 2,257.32	

JOB NATURE

0000 PB	PANEL BEATING-Frt Fender RH.	800.00	377 350
0001 SP	SPRAYPAINT CHARGE	600.00	400 500
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30
		SUB-TOTAL : 1,480.00	

Steve (LKK) 14/4/21, 4.00pm

WZ PL

P/P

My PR say
 3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: