


ASS. REC. BY: Steve REF: CS/CT/121004741/E9F3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SJA 7375Z
at Workshop m/s CYCLE & CARRIAGE
of _____
Insured: GBC 2203D
Policy No. DMCVSNW00066142009
Claims No. SNM21D202130/C02
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJA 7375Z Yr Regn: 23/9/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Sorrento c.c. 2199
Colour: Grey A/C: Insured / Std / NI / N
Sp. Reading: 41502 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KNAPH 818 MKS 23944
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: NII / 8/Rim / STD A/Rim or
Tyre Size: F: 235/55 2019
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 13/4/21 D.O.I. 15/4/21
Survey held at Cycle & Carriage
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-130K</u>
<u>16/4/2021 @ 4.54pm</u>	<u>Revised to Jenny Lew via Merimon.</u>
<u>29/04/21 @ 10.22pm</u>	<u>Steve finalised with Rene final fig \$10376, 5 days. (Red \$6464, 38%)</u>

File/Time, File, Pass to? ☐ : Prel. Report
31/05 Typist ☐ : Final Report
File/Time, File Return to?

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS, \$	
Provision	
Collect	
TOTAL	

31/05/2021 : MER-TP
Total Sum : 10376



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPIING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Mr Boey Teck Meng Reg No/Reg Date SJA7375Z / 23/09/2019 Date In/Mileage 13/04/2021/ 41310 Chassis No KNAPH81BMK5523944 Engine No D4HBJH205584 Make/Model KIA/SORENTO 2.2 A SR D EGD Colour/Trim KLG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	14/04/2021/ 11:34	DS	303 / Renemer	10198			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088							250.00
	DIAGNOSTIC/SCANNING							80 100.00
S	MIPNT88088							300.00
	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							220.00
S	MIPNT88088							100.00
	TO REPLACE TAILGATE GLASS							320 640.00
S	MIPNT88088							1 640.00
	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS							100 200.00
S	MIPNT88088							1280 3840.00
	TO APPLY SELANT KIT IN NEW TAILGATE GLASS							1100 2750.00
S	MIPNT88088							1 500.00
	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS							
S	MIPNT88088							
	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							
	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS							
S	MIPNT88088							
	TO REPLACE TAILGATE,UPR & LWR REAR BUMPER,SKID PLATE,BRACKETS,CLIPS, FOG LAMP & COVER,SENSORS,GARNISH,ETC							
	-TO LHR OTR FENDER & REPAIR REAR END PANEL							
	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT98088							
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088							
	CERAMIC COATING (OWNER PURCHASED)							
M	KS 86320 C5 100	EMBLEM-KIA	✓	n/c	1.00	69.00	0.00	69.00
M	KS 86310 C5 010	EMBLEM-SORENTO	—	n/c	1.00	28.00	0.00	28.00
M	KS 86333 C5 000	EMBLEM - ECO DYNAMIC	—	n/c	1.00	37.00	0.00	37.00
M	KS 87110 C5 000	GLASS ASSY - TAILGAT	✓	n/c	1.00	690.00	0.00	690.00
M	KS 86114 2L 000	PAD-WINDSHIELD	—	n/c	4.00	17.00	0.00	68.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Mr Boey Teck Meng Reg No/Reg Date SJA7375Z / 23/09/2019 Date In/Mileage 13/04/2021/ 41310 Chassis No KNAPH81BMK5523944 Engine No D4HBJH205584 Make/Model KIA/SORENTO 2.2 A SR D EGD Colour/Trim KLG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	14/04/2021/ 11:34	DS	303 / Renemer	10198				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	KS	86114	3D	000	PAD-W/SHLD GLASS	6.00	2.00	0.00	12.00
M	KS	87115	C5	000	STOPPER-RR WINDOW GL	2.00	4.00	0.00	8.00
M	KS	73700	C5	121	PANEL ASSY-TAIL GATE	1.00	1445.00	0.00	1445.00
M	KS	92403	C5	600	LH INR LAMP ASSY-REA	1.00	827.00	0.00	827.00
M	KS	92401	C5	600	LH OTR LAMP ASSY-REA	1.00	493.00	0.00	493.00
M	KS	86611	C5	510	UPR COVER-RR BUMPER	1.00	605.00	0.00	605.00
M	KS	86612	C5	500	LWR COVER - REAR BUM	1.00	565.00	0.00	565.00
M	KS	86665	C5	510	SKID PLATE - REAR BU	1.00	103.00	0.00	103.00
M	KS	06032	50	037A	FASTERNER- BUMPER	10.00	2.00	0.00	20.00
M	KS	86661	C5	000	LH BRACKET ASSY - RE	1.00	22.00	0.00	22.00
M	KS	86662	C5	000	RH BRACKET ASSY - RE	1.00	22.00	0.00	22.00
M	KS	86653	C5	500	LH COVER-BLANKING RR	1.00	44.00	0.00	44.00
M	KS	92405	C5	510	LH LAMP ASSY-REAR FO	1.00	129.00	0.00	129.00
M	KS	86654	C5	500	RH COVER-BLANKING RR	1.00	44.00	0.00	44.00
M	KS	92406	C5	510	RH LAMP ASSY-REAR FO	1.00	129.00	0.00	129.00
M	KS	96890	C5	500B 4U	ULTRASONIC SENSOR-S.	4.00	187.00	0.00	748.00
M	KS	96890	C5	200	OTR ULTRASONIC SENSO	2.00	187.00	0.00	374.00
M	KS	86690	C5	500	UNDER COVER ASSY-RR	1.00	30.00	0.00	30.00
M	KS	87741	C5	000	LH SIDE GARNISH ASSY	1.00	49.00	0.00	49.00
M	KS	91885	C5	130	WIRING HARNESS-R.P.A	1.00	357.00	0.00	357.00
M	KS	86630	C5	510	RAIL ASSY-REAR BUMPE	1.00	341.00	0.00	341.00
M	KS	95420	C6	500	ANTENNA ASSY-SMARTKE	1.00	33.00	0.00	33.00
M	KS	86667	C5	500	CAP-RR HOOK	1.00	8.00	0.00	8.00

Z NOTES

ACCIDENT ON 13/04/2021 ALONG LOYANG AVENUE FILTERING TO TPE

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP#: GBC2203D

TP INS: CHINA TAIPING

Steve (LKR) wL PL
15/4/21, 11.00am 5 dgs
P/P
My BL 02LKR Auto Consultants hence notify
the insurer of the following:

- Confirm & accepted by before/after spray painting
- To spray damaged part(s) during resurvey
 - Repairs are subject to confirmation
 - The survey is on a "Without Prejudice" basis
 - No modification(s) is allowed
 - Any item(s) must be resurveyed and

Authorized signatory and company stamp

Parts	7,300.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,540.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	16,840.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SC0N214D0006 / Cycle & Carriage Fulco Motor Dealer Pte Ltd
ENTRY DATE & TIME: 13/04/2021 18:10 (SGT)
SUBMITTED BY: Renemer Bagang
VERSION: 1 (13/04/2021 18:10 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/04/2021 18:10 (SGT)
Date of Accident 13/04/2021 13:53 (SGT)
Exact Location of Accident Loyang Ave, Singapore
Additional Location Information SLIP ROAD JOINING TPE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJA7375Z

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner No
NRIC No BOEY TECK MENG
Email Address SXXXX931B
Mobile Phone No richardboey@gmail.com
Alternative Phone No (Phone) +65-97373131
..... (Home) +65-97373131

VEHICLE PARTICULARS

Manufacturer Kia
Model Sorento
Variant
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2200

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number
Cover Note Number 1900164492

DRIVER

Name of Driver BOEY TECK MENG
NRIC No SXXXX931B

Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

14/08/1970
 Indoor
 30/11/1995
 25 YEARS AND 5 MONTHS
 Male
 (Phone) +65-97373131
 (Home) +65-97373131
 richardbooy@gmail.com
 17 Pasir Ris Link #07-46 Singapore

-

518183

Yes

-

No

-

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Head to Rear
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle Involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s)
 soliciting/offering accident claims assistance?

No

2

No

-

Yes

1

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No

No

-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes

Yes

No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 NRIC No
 Contact Number
 Address

GBC2203D

Volkswagen

Caddy

-

Commercial vehicle

SIOW THIAM SUI

SXXXX898Z

(Phone) +65-96505591

-

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




 13/4/21
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


I was driving along Loyang Ave & turning into the slip road joining TPE. When I reached the Filter lane, I stopped my car as there are vehicles ~~from~~ heading to TPE. At this time vehicle GBC 2203D collided to my car rear. Nobody was injured and the ~~accident~~ time of accident was 12.53 pm. Weather condition is good.

Declaration

We declare the foregoing particulars are true in every respect.

 13/4/21
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

