

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE)	Cust No/Name	/Mr Boey Teck Meng
3 Anson Road #16-00	Reg No/Reg Date	The second secon
Springleaf Tower	Date In/Mileage	
Singapore 079909 Attn: Claims Dept. Contact No 63896111	Chassis No	KNAPH81BMK5523944
	Engine No	D4HBJH205584
	Make/Model	KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim	KLG / WK

Account No	Terms	Date/Time	Printed	CSE	Operator		WIP No		
0000018	Credit	14/04/202	21/ 11:34	DS	303 / Reneme	r	10198		
		Descripti	on of Goo	ds / Service	S	Qty	Unit Price	Disc%	Amount
S MIPNT8808									250.0
DIAGNOST		ING							
MIPNT8808									100.0
10 CHECK	ALL LIGH	HTING/WIRI	NG SYSTEM	ON REAR A	CCIDENT				
AFFECTED MIPNT8808									
TO REPLAC		ATE GLASS							300.0
MIPNT8808		TIL ULASS							220.0
		OOL SOLAR	FTIM ON N	EW TAILGAT	224 ID =				220.0
MIPNT8808		002,111	12 011 11	en mileomi	L GENSS				100.0
TO APPLY	SELANT K	KIT IN NEW	TAILGATE	GLASS -					100.0
MIPNT8808	38			052	TIPO /		1		640.0
TO TRANSF	ER TAIL	GATE COMPO	NENTS & M	ECHANISM P	ARTS]		
MIPNT8808					640.0				
TO REMOVE	& RE-IN	NSTALL ALL	CARPETS/	TRIMMING TO	O GIVE WAY				
		REAR ACCI	DENT AFFE	CTED AREAS					
	MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS						200.0		
MIPNT8808		KII UN NE	W & KEPAI	R PANELS					2040
		ATE HDD 9.	MD DEVD	BIIMDED SETI	PLATE, BRACKETS	CLIDS			3840.0
					J FLATE, DRACKETS	o,cliro,			
FOG LAMP & COVER,SENSORS,GARNISH,ETC -TO LHR OTR FENDER & REPAIR REAR END PANEL									
				IDENT AFFE	CTED AREAS				
MIPNT9808									2750.0
SPRAY PAI	INTING ON	N REAR ACC	IDENT AFF	ECTED AREAS	S				
MIPNT8808									500.0
CERAMIC (
(OWNER PL									
KS 86320			MBLEM-KIA			1.00	69.00		69.0
KS 86310			MBLEM-SOR			1.00 1.00	28.00 37.00	0.00	28.0 37.0
KS 86333 KS 87110				CO DYNAMIC - TAILGAT		1.00	690.00	0.00	690.0
KS 86114			LASS ASST AD-WINDSH			4.00	17.00	0.00	68.0
K3 00114	ZL 000	Г	UD-MINDOL	ILLU		4.00	17.00	0.00	00.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE)	Cust No/Name	/Mr Boey Teck Meng
3 Anson Road #16-00	Reg No/Reg Date	0.0 The state of t
Springleaf Tower	Date In/Mileage	13/04/2021/ 41310
Singapore 079909 Attn: Claims Dept. Contact No 63896111	Chassis No	KNAPH81BMK5523944
	Engine No	D4HBJH205584
	Make/Model	KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim	KLG / WK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	erio la colienza	
-0000018	Credit	14/04/2021/ 11:34	DS	303 / Renemer		10198		
		Description of Good	ds / Services		Qty	Unit Price	Disc%	Amount
M KS 86114		PAD-W/SHLD			6.00	2.00	0.00	12.00
M KS 87115		STOPPER-RR	WINDOW GL		2.00	4.00	0.00	8.00
M KS 73700		PANEL ASSY-	-TAIL GATE		1.00	1445.00	0.00	1445.00
M KS 92403		LH INR LAM	ASSY-REA		1.00	827.00	0.00	827.00
M KS 92401		LH OTR LAM	ASSY-REA		1.00	493.00	0.00	493.00
M KS 86611		UPR COVER-			1.00	605.00	0.00	605.00
M KS 86612		LWR COVER -			1.00	565.00	0.00	565.00
M KS 86665		SKID PLATE			1.00	103.00	0.00	103.00
M KS 0G032		FASTERNER-			10.00	2.00	0.00	20.00
M KS 86661		LH BRACKET			1.00	22.00	0.00	22.00
M KS 86662		RH BRACKET	ASSY - RE		1.00	22.00	0.00	22.00
M KS 86653		LH COVER-BI	ANKING RR	11000	152:20	44.00	0.00	44.00
M KS 92405		LH LAMP ASS	Y-REAR FO			129.00	0.00	129.00
M KS 86654		RH COVER-BI			1 4.60	44.00	0.00	44.00
M KS 92406		RH LAMP ASS			1.00	129.00	0.00	129.00
M KS 96890					4.00	187.00	0.00	748.00
M KS 96890		OTR ULTRASO			2.00	187.00	0.00	374.00
M KS 86690		UNDER COVER			1.00	30.00	0.00	30.00
M KS 87741		LH SIDE GAR			1.00	49.00	0.00	49.00
M KS 91885		WIRING HAR			1.00	357.00	0.00	357.00
M KS 86630		RAIL ASSY-			1.00	341.00	0.00	341.00
M KS 95420		ANTENNA ASS			1.00	33.00	0.00	33.00
M KS 86667	C5 500	CAP-RR HOOF	<		1.00	8.00	0.00	8.00
			AVENUE FILT	ERING TO TPE				
TP#: GBC2	2203D	TP INS: CHINA TA	AIPING					
Z NOTES ACCIDENT OWNER CLA REQUIRED TP#: GBC2	AIMING TH REPLACEM	Ī	RD PARTY NT CAR	RD PARTY	INT CAR	RD PARTY	RD PARTY	RD PARTY
Confirm & a	ccepted b	у			Parts			7,300.
					Labour Standard M	onu		0. 0.
								9,540.
					Specialist			0.0 No. 10.0 10.0 10.0 10.0 10.0 10.0 10.0 10
					Others (Lub	,etc)		0.0
					Sundry	CCT)		16 940
		and company stamp			Total (w/o	GST)		16,840.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/04/2021 18:10 (SGT) Date of Accident 13/04/2021 13:53 (SGT) Exact Location of Accident Loyang Ave, Singapore Additional Location Information SLIP ROAD JOINING TPE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

2200

Vehicle Registration Number SJA7375Z

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner **BOEY TECK MENG** NRIC No SXXXX931B Email Address richardboey@gmail.com Mobile Phone No (Phone) +65-97373131 Alternative Phone No (Home) +65-97373131

VEHICLE PARTICULARS

Manufacturer Model Sorento Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive Fleet Policy No Policy Number Cover Note Number 1900164492

DRIVER

BOEY TECK MENG Name of Driver SXXXX931B

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address	14/08/1970 Indoor 30/11/1995 25 YEARS AND 5 MONTHS Male (Phone) +65-97373131 (Home) +65-97373131 richardboey@gmail.com
Address complement	17 Pasir Ris Link #07-46 Singapore
Postcode	
Is the driver the policyholder?	518183
If No, Relationship of the Driver with the Insured	Yes
Does Driver Own Other Vehicles?	- No
Vehicle Registration Number of Other Vehicle Owned by Driver	NO

Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for	attachment?	***************************************	Yes
Was there any video captured by	Car Camera?	404,444,444,444,444	Yes
Was there any audio recorded?			No

Was notice of intended Prosecution given?

DETAILS OF OTHER VEHICLE PROPERTY 1

No

Venicle Registration Number	GBCZZU3D
Vehicle Manufacturer	Volkswagen
Vehicle Model	Caddy
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	SIOW THIAM SUI
NRIC No	SXXXX898Z
Contact Number	(Phone) +65-96505591
Address	

Address complement	
Postcode	
La	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No Of Passanger (Including Date)	- 6
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policytrolder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Acci	ident
	long Loyang Are a funing into jorning The Wen I readly the stopped my ear as there are easily to JTPE. At this time vehicle liked to my car rear. Hobody house he accident was

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SERVICE



COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder

: Boey Teck Meng 22

Period of Insurance Engine No.

: 19 Sep 2019 to 16 Sep 2021

Chasis No.

: D4HBJH205584 / : KNAPH81BMK5523944/

Vehicle No. Cover Note No.

Endorsement No. Issued Date

: 17 Sep 2019

: 1900164492

ABOUT THE COVER

Make/Model

: KIA SORENTO 2,2 A DIESEL

Engine Capacity/Tonnage : 2,199.00 CC **Driver Restriction**

Sum Insured

: Market Value Off Peak Car : No

First Year of Registration : 2019 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Gap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable) Boey Teck Meng - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRES (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

2.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception days stated on this cover note, please contact AIG immediately.

I/We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malassiya) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504624208

FULCOKICP2 - LN

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. **AUTHORISED REPRESENTATIVE** Chin Ee Lut **INSURER ENQUIRY**

Find insurer

Vehicle reg. no.

GBC2203D

Date of Accident

13/04/2021 苗

Reset

% RESULT & RECEIPT

TP Insurer Enquiry	
Insurance	China Taiping Insurance (Sing
Period of Insurance	23/08/2020 - 22/08/2021
Requested By	
Requested Date	

Payment details

Request Amount: \$\$1.87 GST Amount: \$\$0.13

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: **M400017735**