

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

AXA INSURANCE PTE LTD			Ref:	CS3/ASM21004747/Qtce2
			Date:	23/04/2021
ATTN: CHEN XIN	YOU		Code:	ASM
	Policy Particulars	:- (THIRD PART	Y CLAI	M)
Insured Veh.	SBL 9899C	Veh. Inspected		SKA 3103G
Policy No.		Coverage (\$)		0.00
Claim No.	S1M0380P	Excess (\$)		0.00
Assign From	CHEN XIN YOU	Assign Date		14/04/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA 2.4	c.c		2362
Engine No.	HIDDEN	Year of Reg.		2009
Chassis No.	ACR500080782	Colour		GOLD
Odometer	180205 KM	Steering		IN ORDER
Brakes	IN ORDER	Modification		SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
T	Size	Make		Balance
R/H Front Tyre	215/55 R17	DUNLOP		6 mm
L/H Front Tyre	215/55 R17	DUNLOP		6 mm
R/H Rear Tyre	215/55 R17	DUNLOP		6 mm
L/H Rear Tyre	215/55 R17	DUNLOP		6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTI				
5. General Information				
Accident Date	13/04/2021	Inspect Date /	Гіте	15/04/2021 (11:29 AM)
Survey held at	ZOLAR AUTO SERVICES			
	NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21 SINGAPORE 415875			
		Remarks		
	8 SHENTON WAY TOWERSINGAPO ATTN: CHEN XIN Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SU	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHEN XIN YOU Policy Particulars Insured Veh. SBL 9899C Policy No. Claim No. S1M0380P Assign From CHEN XIN YOU Vehicle Part Make & Model TOYOTA ESTIMA 2.4 Engine No. HIDDEN Chassis No. ACR500080782 Odometer 180205 KM Brakes IN ORDER General FAIR Condi Size R/H Front Tyre 215/55 R17 L/H Rear Tyre 215/55 R17 L/H Rear Tyre 215/55 R17 L/H Rear Tyre 215/55 R17 THE VEHICLE SUSTAINED DAMAGES AT THE FR Accident Date 13/04/2021 Survey held at ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHEN XIN YOU Policy Particulars:- (THIRD PART Insured Veh. SBL 9899C Veh. Inspected Policy No. Coverage (\$) Claim No. S1M0380P Excess (\$) Assign From CHEN XIN YOU Assign Date Vehicle Particulars & Condit Make & Model TOYOTA ESTIMA 2.4 c.c Engine No. HIDDEN Year of Reg. Chassis No. ACR500080782 Colour Odometer 180205 KM Steering Brakes IN ORDER Modification General FAIR Conditions of Tyres Kize Make R/H Front Tyre 215/55 R17 DUNLOP L/H Front Tyre 215/55 R17 DUNLOP L/H Rear Tyre 215/55 R17 DUNLOP L/H Rear Tyre 215/55 R17 DUNLOP Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. General Information Accident Date 13/04/2021 Inspect Date / T Survey held at ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHEN XIN YOU Code: Policy Particulars: - (THIRD PARTY CLAI Insured Veh. SBL 9899C Policy No. Claim No. S1M0380P Assign From CHEN XIN YOU Assign Date Vehicle Particulars & Condition Make & Model TOYOTA ESTIMA 2.4 c.c Engine No. HIDDEN Chassis No. ACR500080782 Colour Odometer 180205 KM Brakes IN ORDER Modification General FAIR Conditions of Tyres Size Make R/H Front Tyre 215/55 R17 DUNLOP L/H Rear Tyre 215/55 R17 DUNLOP Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. General Information Accident Date 13/04/2021 Inspect Date / Time Survey held at ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000

5b. **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

Report Ref No. CS3/ASM21004747/Qtce2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser