

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21004748/Gea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	19/11/2021	
	ATTN:YVONNE			Code:	ASM	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YP 2015P	Veh. Inspected	ł	SBR 9981R	
	Policy No.	GA179667	Coverage (\$)		0.00	
	Claim No.	S1M03804	Excess (\$)		0.00	
	Assign From		Assign Date		14/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA NOAH 2.0X	c.c		1986	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	ZRR800415520	Colour		SILVER	
	Odometer	46427 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	FALKEN		6 mm	
	L/H Front Tyre	205/55 R16	FALKEN		6 mm	
	R/H Rear Tyre	205/55 R16	FALKEN		6 mm	
	L/H Rear Tyre	205/55 R16	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DE	ETAILS.				
5.	General Information					
	Accident Date	13/04/2021	Inspection Dat	e	19/04/2021	
	Survey held at	RICO 60 AUTO SERVICES PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKI SINGAPORE 415875	Г			
5a.	5a. Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				