

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/04/2021 12:33 (SGT)
Date of Accident	08/04/2021 18:40 (SGT)
Exact Location of Accident	Eu Tong Sen St, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM868C
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LI BING XUAN DESMOND
NRIC No	SXXXX9701
Email Address	DESMONDLI91@HOTMAIL.COM
Mobile Phone No	(Phone) +65-86861833
Alternative Phone No	+65-86861833

VEHICLE PARTICULARS

Manufacturer	Porsche
Model	Macan
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2997

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA523885
Cover Note Number	-

DRIVER

Name of Driver	LI BING XUAN DESMOND
NRIC No	SXXXX9701

Date Of Birth	21/05/1991
Occupation	Indoor
Date Of Driving Pass	05/07/2011
Driving experience	9 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86861833
Alt. Phone Number	+65-86861833
Email Address	DESMONDLI91@HOTMAIL.COM
Address	BLK 38 LORONG 30 GEYLANG #08-20
Address complement	-
Postcode	398371
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	WIFE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACH
STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC279C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

9/14/21
11:20am

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

[Handwritten Signature]



THANK YOU

Ang Shi Fun Yvonne has successfully logged out.

Your last login date and time was 09 Apr 2021, 15:16:24.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type :	Asset ID :	Asset Owner ID :	Transaction Type :	Transaction Amount(\$\$)
1	Vehicle	SHC279C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
	• Log Date/Time 09 Apr 2021 / 15:17:15				

M/s Lush Automotive Pte Ltd

No. 8 Kaki Bukit Avenue 4, #03-47 Premier@Kaki Bukit, Singapore 415875

Name : LI BING XUAN DESMOND
Address : C/o No. 8 Kaki Bukit Avenue 4, #03-47
: Premier@Kaki Bukit, Singapore 415875

Vehicle No. : SLM868C
Accident date : 8 April 2021

Final Repair Bill for Vehicle No. SLM868C

To supply labour and replaced parts,
labour charges for repairing, knocking,
panel-beating, welding and respray
(Lumpsum repair)

S\$ 4,900

Singapore Dollars: FOUR THOUSAND AND NINE HUNDRED ONLY



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-01, Thong Chai Building, Singapore 169874
Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21
Date : 05 May 2021
Vehicle no : SLM 868C

To: Li Bing Xuan Desmond
c/o 8 Kaki Bukit Ave 4
#03-47, Premier @ Kaki Bukit
Singapore 415875

INVOICE

PARTICULARS

AMOUNT

Registration No. : SLM 868C
Date of accident : 08 April 2021
Make / Model : Porsche Macan S 3.0 AT 4WD
Invoice No. : 10010

Being work done and services rendered as follows:

- ✓ Inspection of Vehicle
- ✓ Re-Inspection
- ✓ Appraisal Report
- ✓ 28 Colored Photographs
- ✓ Transport Charges

SGD 508.00

TOTAL SGD 508.00

Dollars: **Five Hundred and Eight Only**

(Cheque should be crossed and make payable to "TY5 CONSULTANCY")

TY5 CONSULTANCY



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21

Date : 05 May 2021

Vehicle no : SLM 868C

To: Li Bing Xuan Desmond
c/o 8 Kaki Bukit Ave 4
#03-47, Premier @ Kaki Bukit
Singapore 415875

VEHICLE INSPECTION REPORT

Name of Workshop : Lush Automotive Pte Ltd
Place of inspection : 8 Kaki Bukit Ave 4 #03-47, Premier @ Kaki Bukit, Singapore 415875
Date of Accident : 08 April 2021
Date of Inspection : 14 April 2021

VEHICLE PARTICULAR

Registration No.	: SLM 868C	Chassis Frame No.	: WP1ZZZ95ZFLB66995
Make / Model	: Porsche Macan S 3.0 AT 4WD	Engine No.	: 018245
Year of Registration	: 2015	Odometer Reading	: 68,744 KM
Class / Type	: SUV	Colour	: Blue

VEHICLE CONDITION

General Condition	: Very Good	Steering	: Serviceable
Paintwork	: Very Good	Foot/ Parking Brake	: Serviceable

TYRE CONDITION

	Size	Thread Balance
Front L/H :	RADAR 235 / 60 ZR18	9mm
Front R/H :	RADAR 235 / 60 ZR18	9mm
Rear L/H :	RADAR 235 / 60 ZR18	9mm
Rear R/H :	RADAR 235 / 60 ZR18	9mm

* The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 4,406.00	\$ 3,965.40
Labour	\$ 2,680.00	\$ 2,150.00
	<u>\$ 7,086.00</u>	<u>\$ 6,115.40</u>

TY5 Recommendation

Lump Sum Repair :
\$ 4,900.00

Estimated Repair Duration :

4

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21

Date : 05 May 2021

Vehicle no : SLM 868C

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
LIST ITEMS:-					
1	1 pc	front bumper	deformed	\$ 2,920.00	\$ 2,920.00
2	1 pc	front bumper l/h side grille	scratched	\$ 259.00	\$ 259.00
3	1 pc	front bumper l/h fog lamp	scratched	\$ 647.00	\$ 647.00
4	1 pc	front bumper l/h side retainer	necessary	\$ 290.00	\$ 290.00
5	1 pc	front bumper r/h side retainer	necessary	\$ 290.00	\$ 290.00
6	1 pc	l/h front fender	damaged	repair	repair
				\$ 4,406.00	\$ 4,406.00
Less 10%					\$ 440.60
				\$ 4,406.00	\$ 3,965.40

Total \$ 4,406.00 \$ 3,965.40



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21

Date : 05 May 2021

Vehicle no : SLM 868C

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
		B/F		\$ 4,406.00	\$ 3,965.40
7		To panel beat and renewal of all necessary damaged body parts		\$ 1,000.00	\$ 800.00
8		To check wiring and rewire		\$ 60.00	\$ 50.00
9		To perform 4 wheel alignment		\$ 120.00	\$ 100.00
10		To perform car wrap on affected area.		\$ 700.00	\$ 600.00
11		To putty and spray-paint of affected areas		\$ 800.00	\$ 600.00
				\$ 2,680.00	\$ 2,150.00

Total **\$ 7,086.00** **\$ 6,115.40**



TY5 CONSULTANCY

(Registration No.: 53429873C)

Address : 50 Chin Swee Road #09-01, Thong Chai Building, Singapore 169871


Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10010/0868/TP/04.21
Date : 05 May 2021
Vehicle no : SLM 868C

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered **Diagonally to the LH Side from rear to front; left to right;** portion of the vehicle.



(Please refer to the list and survey photographs as attached for more information)

ASSESSMENT RECOMMENDATIONS

COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 4,406.00	\$ 3,965.40
Labour	\$ 2,680.00	\$ 2,150.00
	<u>\$ 7,086.00</u>	<u>\$ 6,115.40</u>

TY5 Recommendation

Contract Lump Sum of \$ 4,900.00
Estimated Repair Duration : 4 working days
(excluding Sat, Sun & Public Holidays)

Enclosed No. Of Photograph : 28
(at the time of static inspection)

Our attached assessment schedule has been checked throughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repairer has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repairer to proceed with the repairs.

The survey was done on a **Without Prejudice Basis** and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no. 10010

TY5 CONSULTANCY

TERRENCE HONG
AUTOMOTIVE SURVEYOR

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen (14) days from the date hereof. Otherwise this revised amount shall be treated as valid.*







