Surveyor:

REF: CS1/ASM21004752/Vvy3

Special Instruction:

ASSIGNMENT (Office)

From (Person): TAN JUN HONG of AXA Date/Time: 29.11.2021

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop: LUSH AUTOMOTIVE

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLM 868C Insured: SHC 279C

at Workshop m/s LUSH AUTOMOTIVE Tel:

of 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT

Policy No: Claim No: S1M037KW

Sum Insured: Excess:

Make of Veh: D.O.A. 08/04/2021

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** ,days (Red $ / %; Original 7 days)

Date/Time: 29.11.2021 **Submit Final Fig** 4,900 ,4 days (Red $ / %; Original days)

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to