

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 To Inspect Vehicle No: SKS 378E  
 at Workshop m/s: K K Hin  
 of \_\_\_\_\_  
 Insured: SG 3030G  
 Policy No. \_\_\_\_\_  
 Claims No. BUS/04/21/1026  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 04 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP / 24 HRS  
10/23  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKS 378E Yr Regn: 12, 08  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or Wagon  
 Make: Honda Edix c.c. 1998  
 Colour: White AC: Insured / Std / Nil / NA  
 Sp. Reading: 238333 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: BE 31 203634  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rlm / STD / Rlm or \_\_\_\_\_  
 Tyre Size: F: Pir 205/55R16  
 R: Yoko  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 5 mm Rear R/Bal. 6 mm  
 L/Bal. 5 mm L/Bal. 6 mm  
 D.O.A. 4/4/21 D.O.I. 3/8/2021  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
N/S 1st body  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/8</u>	<u>UIC Rep @ 1200 4 repair days</u>
	<u>(RED \$1910.40; 61%)</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 1) 30/9 TYPIST  
 Date/Time, File Return to?

Days Of Repair: 4  
 Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
S + RS:	
Others:	
TOTAL	

Report Format: TP  
 Lump Sum / I.B.T. (\$) 1200

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

# W. Kim Hin AUTO REPAIR

## 金興(鐘)汽車私人有限公司

160 Sui Ming Drive, #02-20,  
Sui Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 31749

Date : 08-Apr-2021

Vehicle Insured : SG 3030 G  
Accident Date : 04-Apr-2021

Our Ref : 021127 (SMRT) / QUEK

PAGE : 1

IVAN GOH KIM LENG (MR)  
Singapore

*Not Noted  
11 By \$12 each  
Resurvey After Paint  
2 days*

### ESTIMATED COST OF REPAIR FOR HONDA EDIX 2.0X (A) (2008) SKS378E

1 pc LH wing mirror assy	cm	680.00	✓
1 pc LH front fender	R	550.00	✓
1 pc LH front fender inner shield	in	100.00	✓
8 pcs LH front fender inner shield clips	@ S\$ 3.50	in	28.00 ✓
1 pc LH front bumper side retainer	in	30.00	✗
		-----	
		1,388.00	
Less 20% :		-277.60	
		-----	
			1,110.40

1 pc LH front door company advertisement sticker *(Art) in* 400.00 sn/100.00

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts. 650.00 *2501*

To putty and respray on affected portions. 950.00 *6601*

Total : S\$ 3,110.40

Singapore Dollars Three Thousand One Hundred and Ten and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 05/04/2021 21:05 (SGT)  
Date of Accident ..... 04/04/2021 20:20 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... YISHUN AVE 7  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKS378E

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... IVAN GOH KIM LENG  
NRIC No ..... SXXXX732G  
Email Address ..... KIMLENG8@HOTMAIL.COM  
Mobile Phone No ..... (Phone) +65-96918301  
Alternative Phone No ..... (Home) +65-96918301

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Edix  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 0

### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5106185134-02  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... IVAN GOH KIM LENG  
NRIC No ..... SXXXX732G

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
 Policyholder's Signature / Date & Time

  
 Driver's Signature (if driver is not the policyholder) / Date & Time

  
 Witnessed by Reporting Centre Personnel

**Sketch Plan**




A: SKS378 E  
 B: SG 3030 G

**Describe Circumstances of the Accident**


I was driving along Vishnu Ave 7 (Sembawang Rd). I was stopping behind the yellow box waiting for green arrow light so as to move on. When the traffic turn Green I started to move the bus inside the box but suddenly speed up cut his way through my way without looking out for safety. I have to highlight this, I was moving first when the Green light appear after that follow by the Bus. The driver just speed up very fast as I'm driving slow enough to monitor the <sup>road</sup> condition around me. My left rear side mirror was hit and my ~~body~~ Car body above the left front tyre was badly scratch & dented.

**Declaration**

We declare the foregoing particulars are true in every respect.

 08/08/2021  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel