

CS3

ASS. REC. BY: Steve

REF: CS/AIG 21004757/E&F3

PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD (TP) WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 2070075740
 Claims No. 1699091010SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMV1817J Yr Regn: 21/9/20
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: KIA Cerato c.c 1591
 Colour: Grey A/C: Insured / Std / NI / N
 Sp. Reading: 74121 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: KNAF5416ML5086978
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: NII / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45R17
 R: 4
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or 3 Nexen
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 14/4/21 D.O.I. 15/4/21
 Survey held at HACK Eng
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision

| | |
|-----|-----|
| N/S | O/S |
| | x |

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

| Date / Time | Action / Instruction |
|-------------|----------------------|
| | MV-81K |
| 19/04/21 | Submit DAR. |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Prell. Report
 : Final Report
 19/04 Typist
 Date/Time, File Return to?

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| \$ + RS \$ | |
| Photos | |
| Others | |
| TOTAL | |

Rep. Format: MER-DAR
 Comp. Sign / U.C. / C

Alon (CON)

(1) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Deformed (8) Dislodged (9) Dented (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (2) Repair (3) Check (4)
 (5) Plus Consistent (C)

Aug 2005

Vehicle No:

SMV 1817 J

Rear Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|----------------------------------------------------|-------|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | BR | ✓ | |
| 1142 | 993085 | Rear Bumper Upper | BR | ✓ | |
| 1143 | 993017 | Rear Bumper Lower | BR | ✓ | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993101 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | IPC | ✓ | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | BR | ✓ | 2 |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Base Side <i>garnish RH</i> | CUT | ✓ | |
| 1155 | 993026 | Rear Bumper Moulding <i>RH top</i> | CUT | ✓ | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | Start | ✓ | |
| 1159 | 993327 | Rear End Panel | | R | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp <i>RH</i> | CUT | ✓ | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | OO | ✓ | |
| 1171 | 991328 | Bootlid Emblem | nlc | ✓ | 4 |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector <i>Centre</i> | | ? | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | BR | ✓ | |
| 1177 | 995243 | Bootlid Lock | BT | ✓ | |
| 1178 | 999377 | Bootlid Rubber | | ? | |
| 1179 | 999382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 993323 | Triangle Breakdown Sign | | | |
| 1208 | 999507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | R |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993491 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1136 | 990247 | Sticker | | | |

5 repair days