

CS3/AIG 21004760/ETF3

PRS

ASSIGNMENT

Veh No: STF 6553 G Yr Regn: 6/6/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima c.c. 2362

Colour Black , A/C: Insured / Std / NI / N

Sp. Reading: 161798 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: ACR 507961869

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO) or 2

Front _____ Rear _____

R/Bal. S mm R/Bal. S mm

L/Bal.	\$		mm	L/Bal.	\$		mm
--------	----	--	----	--------	----	--	----

D.O.A. 13/4/21 D.O.I. 15/4/21

Survey held at Maye 13

Vehicle: IN / OUT

Date: Person Contacted:

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

[illegible]

☐ : Prell. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Fructus

Others:

7075L

Add Fee: ☐ : Site Insp (\$ _____) _____ \$ + RS. _____ \$
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others:
☐ : Weekend (\$ _____)

Condition Codes

(1) New (2) Used (3) Damaged (4) Cracked (5) Cut (6) Scratched
(7) Stained (8) Discoloured (9) Discoloured (10) Broken (11) Necessary
(12) Missing (13) Not (14) Incomplete (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (R) (3) Check (C)
(4) Not Consistent (N/C)

Aug 2005

Rear Particular

Vehicle No:

SJF 6553G

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	993633	Rear Bumper	NO		
1142	993635	Rear Bumper Upper			
1143	993637	Rear Bumper Lower			
1144	993638	Rear Bumper Side			
1145	993639	Rear Bumper Tow Cover			
1146	993641	Rear Bumper Clips	MC		
1147	993642	Rear Bumper Bracket			
1148	993643	Rear Bumper Side Retainer	OR		
1149	993645	Rear Bumper Reinforcement			
1150	993647	Rear Bumper Beam			
1151	993648	Rear Bumper Sponge			
1152	993649	Rear Bumper Damper			
1153	993650	Rear Bumper Protector			
1154	993651	Rear Bumper Pad			
1155	993652	Rear Bumper Moulding			
1156	993653	Rear Bumper Reflector			
1157	993654	Rear Bumper Lower Spoiler			
1158	993655	Reverse Sensor			
1159	993656	Rear End Panel			
1160	993657	Rear End Panel Top Garnish			
1161	993658	Rear End Panel Inner Trim			
1162	993659	Boot Compartment Inner Trim			
1163	993660	Rear LH Tail Lamp			
1164	993661	Rear LH Tail Lamp Garnish			
1165	993662	Rear LH Tail Lamp Panel			
1166	993663	Rear RH Tail Lamp			
1167	993664	Rear RH Tail Lamp Garnish			
1168	993665	Rear RH Tail Lamp Panel			
1169	993666	Rear Apron Panel			
1170	993667	Bootlid			
1171	993668	Bootlid Emblem			
1172	993669	Bootlid Handle			
1173	993670	Bootlid Moulding			
1174	993671	Bootlid Reflector			
1175	993672	Bootlid Lamp LH			
1176	993673	Bootlid Lamp RH			
1177	993674	Bootlid Lock			
1178	993675	Bootlid Rubber			
1179	993676	Bootlid Hinge			
1180	993677	Bootlid Spoiler			
1181	994543	Tailgate			
1182	994544	Tailgate Emblem	MC		
1183	994545	Tailgate Outer Handle			
1184	994546	Tailgate Moulding			
1185	994547	Tailgate Garnish			
1186	994548	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994550	Tailgate Protector			
1189	994551	Tailgate Wiper Arm			
1190	994552	Tailgate Wiper Blade			
1191	994553	Tailgate Wiper Nozzle			
1192	994554	Tailgate Wiper Motor			
1193	994555	Tailgate Glass			
1194	994556	Tailgate Glass Rubber			
1195	994557	Tailgate Glass Moulding			
1196	994558	Tailgate Glass Sealant			
1197	994559	Tailgate Lock			
1198	994560	Tailgate Rubber			
1199	994561	Tailgate Hinge			
1200	994562	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	993785	Spare Tyre Panel			
1204	993786	Spare Tyre			
1205	993787	Spare Tyre Lock Screw			
1206	993788	Spare Tyre Cover			
1207	993789	Triangle Breakdown Sign			
1208	993790	CD Changer Assy			
1209	993791	Antenna			
1210	993792	Centre Exhaust Pipe Assy			
1211	993793	Centre Exhaust Mounting			
1212	993794	Rear Exhaust Pipe			
1213	993795	Rear Exhaust Chrome Pipe			
1214	993796	Rear Exhaust Mounting			
1215	993797	Rear Exhaust Heat Shield			
1216	993798	Rear LH Chassis Member			
1217	993799	Rear RH Chassis Member			
1218	993800	Rear LH Fender			
1219	993801	Rear LH Fender Protector			
1220	993802	Rear LH Fender Inner Panel			
1221	993803	Rear LH Fender Inner Trim			
1222	993804	Rear LH Fender Inner Garnish			
1223	993805	Rear LH Fender Inner Shield			
1224	993806	Rear LH Mudflap			
1225	993807	Rear LH Wheel Rim			
1226	993808	Rear LH Rim Cover			
1227	993809	Rear LH Tyre			
1228	993810	Rear RH Fender			
1229	993811	Rear RH Fender Protector			
1230	993812	Rear RH Fender Inner Panel			
1231	993813	Rear RH Fender Inner Trim			
1232	993814	Rear RH Fender Inner Garnish			
1233	993815	Rear RH Fender Inner Shield			
1234	993816	Rear RH Mudflap			
1235	993817	Rear RH Wheel Rim			
1236	993818	Rear RH Rim Cover			
1237	993819	Rear RH Tyre			
1238	993820	Rear Fender Extension Panel LH			
1239	993821	Rear Fender Extension Panel RH			
1240	993822	Rear Fender Inner Top Garnish			
1241	993823	Rear Fender 1/4 Glass			
1242	993824	Rear Fender 1/4 Glass Rubber			
1243	993825	Rear Fender 1/4 Glass Sealant			
1244	993826	Rear Windscreen Glass			
1245	993827	Rear Windscreen Rubber			
1246	993828	Rear Windscreen Moulding			
1247	993829	Rear Windscreen Sealant			
1248	993830	Third Brake Light			
1249	993831	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992169	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

3 repair days