

Your Ref: 18/18/19/VC10/274740

Date: 28th June 2021

Our Ref: CS1/LPM21004765/Kqf3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
NO. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHA 276X
INSURED VEHICLE: JMR 9208
ACCIDENT DATE: 05/12/2018**

We thank you for your instruction on 15/04/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHA 276X from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHA 276X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHA 276X
Make & Model	: Hyundai I40 1.7 CRDI F/L AT
Year of Registration	: 2015
Chassis Number	: KMHLB41UMGU079580
Engine Capacity	: 1685 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.