

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21004768/Uba3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	10/08/2021	
	ATTN:LYNN			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMH 6790S	Veh. Inspected	i	SLZ 8371Y	
	Policy No.	VPA/P2246554	Coverage (\$)		0.00	
	Claim No.	S1M0382Y	Excess (\$)		0.00	
	Assign From		Assign Date		15/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FIT (A)	c.c		1317	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	GK31316647	Colour		BLUE	
	Odometer	60833 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	HIFLY		6 mm	
	L/H Front Tyre	175/70 R14	HIFLY		6 mm	
	R/H Rear Tyre	175/70 R14	HIFLY		6 mm	
	L/H Rear Tyre	175/70 R14	HIFLY		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/04/2021	Inspection Dat	e	15/04/2021	
	Survey held at	FASTECH AUTO PTE LTD	•			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		6 Worki	ng Days	