

22/03/2002

CS3/MSG19009064/T1qf3-1

ASS. REC. BY:

REF: ~~CS3/MSG19009064/T1qf3-1~~ Special Instruction:

Surveyor: Tau Hing

ASSIGNMENT (Office)

From (Person): Elaine Nga Siu Mei of MSG Date/Time: 23.5.19 10:30 AM

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 3326L Insured: SMK 9150D

at Workshop m/s MJ Car Consultant Tel: 8866 8832
of 53 Yee Ave 1 # 01-33

Policy No: 29120056MCX Claim No: 594159

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14.5.19
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{sup} H.O.D. Endorsement: _____

Date/Time: 23.5.19 10.54 AM Person Contacted: Hui chin Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SJU 3326L - NA/INC19008581/K4 R.O.A - 14/05/2019
	SMK 9150D - NA/INC19008581/K4 D.O.A - 14/05/2019
12/6/19 @ 12:00pm	Informed Elaine Nga, we are pending estimate from repairer.
05/7/19 @ 2:00pm	checked with Hui chin, this case only take photos due to car with SD/SD issued by insurance.
	Dismantle: 17/6/2019

reimburse

ISS. REC. BY: *Tayfiri*

REF: ~~MS16~~ CS3/MSG19009064/T1qf3-1

LOE 2019 Nov

ASSIGNMENT

From: _____ Date: **14/6/19**

Estimated Cost: _____

OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SJU 3326L**

at Workshop n/s **WG APPRAISAL**
~~My Car Consultant~~

of **53 ubi Ave 1 # 01-33**

Insured: **SMK 9150D**

Policy No. **29120056MCX**

Claims No. **594159**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SJU 3326L** Yr Regn: **2009, Nov**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: **BMW 318I** c.c. **1995**

Colour: **Grey** A/C: **Insured / Std / NI / NA**

Sp. Reading: **187974** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **WBAPF720601A145478**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: **Nil / S/Rim / STD A/Rim or** **205/55R16**

Tyre Size: F: _____ R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **1up**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. _____	D.O.I. 14/6/19c4pm

Survey held at **My Car**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	4600 \$7000 3019F , 7 days
	L/S \$3600, 3 DAYS. (RED \$1500; 29%)

Date/Time, File Pass to? : Preli. Report

1) **20/4 TYPIST** : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: **PRE MER-TP**

Lump Sum / _____ **\$3600**

Days Of Repair: **≠ 3**

Resurvey No. of Trip: **+**

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee: **100**

Transportation: _____

S + RS: SI _____

Photos: _____

Others: **+**

TOTAL: **111**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	22 May 2019		23 May 2019 10:30 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ASIA EXPRESS CAR RENTAL PTE LTD , Co. Reg. No.: 201116882D								
Main Claimant:	LEE KHAI ANG , ID: S1698019F								
Vehicle Reg. No.:	SJU3326L	Date of Loss:	14/05/2019 11:00 - :59 [113 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 594159	Policy/Cover Note No.:	29120056MCX (Comprehensive) Coverage: 25/03/2019 - 24/03/2020						
Vehicle Reg. No. (Insured):	SMK9150D	Policy No. (Claimant):	5105460236						
		Excess:							
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 24/05/2019]								
Driver/Custodian (Insured):	RAMIDUAN BIN RAHMAT (), NRIC: S7641718J Email:								
Adj Asg. Remarks:	DISAGREED, DISPUTE, CHOOSE LKK.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 17 June 2019 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SJU 3326L (YOUR REF: 594159)

This mail is associated with :
***SJU3326L (594159)**
[SMK9150D]
TP
LEE KHAI ANG
May 14 2019 11:00AM
[ASIA EXPRESS CAR RENTAL PTE LTD]
My Car Consultant Pte Ltd

Dear Elaine,

Please be informed that we have inspected the vehicle SJU 3326L on 14/06/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8019F
Vehicle Details	
Vehicle No.:	SJU3326L
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR
Primary Colour:	Green
Manufacturing Year:	2009
Engine No.:	A769I574N46B20BZ
Chassis No.:	WBAPF72060A143478
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$35,453.00
Original Registration Date:	30 Nov 2009
First Registration Date:	30 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$35,453.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2019
PARF Rebate Amount:	\$17,726.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,901.00
COE Rebate Amount:	\$774.00
Total Rebate Amount:	\$18,500.00

The information contained herein is correct as at 06 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2019 10:10
Date Of Accident	14/05/2019 11:20
Exact Location Of Accident	25 SYNERGY @ KB (S417800) BEFORE RAMP / 1 LEVEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU3326L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	LEE KHAI ANG
NRIC No	S1698019F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83685720
Alternative Phone No	OTHERS-83685720

Vehicle Particulars

Manufacturer	BMW
Model	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105460236
Cover Note Number	

Driver

Name of Driver	LEE ZHENG HUI
NRIC No	S9737520H
Date Of Birth	24/10/1997
Occupation	OUTDOOR
Date Of Driving Pass	30/06/2016
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83685720
Fax Number	
Contact Number	OTHERS-83685720
E-Mail Address	NOEMAIL

Address	83 PASIR RIS HEIGHTS #11-01
Postcode	519283
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK9150D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 - 15/5/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		23 May 2019 10:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ASIA EXPRESS CAR RENTAL PTE LTD , Co. Reg. No.: 201116882D								
Main Claimant:	LEE KHAI ANG , ID: S1698019F								
Vehicle Reg. No.:	SJU3326L	Date of Loss:	14/05/2019 11:00 - :59 [113 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 594159	Policy/Cover Note No.:	29120056MCX (Comprehensive) Coverage: 25/03/2019 - 24/03/2020						
Vehicle Reg. No. (Insured):	SMK9150D	Policy No. (Claimant):	5105460236						
		Excess:							
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 24/05/2019]								
Driver/Custodian (Insured):	RAMIDUAN BIN RAHMAT (), NRIC: S7641718J Email:								
Adj Asg. Remarks:	DISAGREED, DISPUTE, CHOOSE LKK.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU3326L (594159)
 [SMK9150D]
 TP
 LEE KHAI ANG
 May 14 2019 11:00AM
 [ASIA EXPRESS CAR RENTAL PTE LTD]
 My Car Consultant Pte Ltd



Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
2	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
3	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
4	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
5	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
6	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
7	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
8	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
9	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
10	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
11	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
12	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
13	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
14	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
15	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
16	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
17	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
18	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
19	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
20	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
21	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
22	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
23	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
24	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
25	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
26	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
27	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
28	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
29	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
30	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
31	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
32	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
33	15/07/19 11:46	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
34	29/08/19 17:05	Photographs of Damaged Parts	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
35	29/08/19 17:05	Photographs of Damaged Parts	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
36	29/08/19 17:05	Photographs of Damaged Parts	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
37	29/08/19 17:05	Photographs of Damaged Parts	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	29/08/19 17:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	15/05/19 10:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	15/05/19 10:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	15/05/19 10:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	15/05/19 10:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/05/19 10:22	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	15/05/19 10:22	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="text-align: right;"> ^ v </div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19009064/T1CD3E2

Date: 03/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29120056MCX
Claimant Vehicle No : SJU3326L	Insured Vehicle No :	SMK9150D
Date of Loss: 14/05/2019	Nature of Claim:	TP Claim No: 594159

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU3326L	Engine No:	A769I574N46B20BZ
Make & Model:	BMW 318I, 2.0 L (A)	Chassis No:	WBAPF72060A143478
Reg. Date:	30/11/2009 (Man. Year: 2009)	Odometer:	187974 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	14/06/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2019)
Parts: 143	BMW 318I 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU3326L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >