

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM21004771/Apa3q2	
	8 SHENTON WAY AXA TOWERSING		Date:	16/07/2021	
	ATTN:RICHARD A	NG	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7217E	Veh. Inspected	SJA 6655Y	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M0382H	Excess (\$)	0.00	
	Assign From		Assign Date	15/04/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ E200	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WDD2120342B134079	Colour	SILVER	
	Odometer	138788 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	245/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	245/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	245/45 R17	GOODYEAR	6 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/04/2021	Inspection Date	15/04/2021	
	Survey held at	SMARTONE AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				