

Our Job Ref No	8	305463173	
	-4		
Date	• :	20/04/21	
Date			

Date : 20/04/21		59 Loya	ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
FINA	LIZATION FORM	Fax: 654	16 8156			
То	:LKK	Fax:				
Attn	: TAUFIKH					
Vehi	cle Reg No. : SHA6571D	x	09/04/21			
The	survey and estimates of the repairs of the above-me	entioned vehicle are as follows:-				
Z	The repair job shall bill to:	NTUC	XE4210Z			
2.	The finalized amount shall be:					
	(a) Spare Parts after List discount					
	(b) Labour Charges					
	Total for Part-By-Part Repair Cost					
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost		\$1,600.00			
3.	Estimated normal period for repairs:	2 working days.				
4.	We shall treat the above amount as Correct and working days	d Confirmed if there is no reply	from you within 7			
5.	Thank you for your assistance.	We confirm the esting finalized amount				
	Signature :	Signature:て	aufikh			
	Name : CHIANG		ufikh			
	Tel 62148314	Date :20	0/5/21			
	Fax : 65468156	_				
For O	fficial Use Only					

ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees	+	58.0		
4. LTA Search Fee	\$7.49/\$2.00			
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:				