

ASS. REC. BY:

REF:

AGZ/21004788/KV

Kenneth

ASSIGNMENT

18

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

C10009828/CH

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBL 9899C

Yr Regn:

10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Harrier

c.c

1998

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

4802P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTEKB3G1480J002942

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/4/21

D.O.I.

18/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/5 11:12 AM @ 80501 (Red 11,459.12, 58%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/04/2021 20:01 (SGT)
Date of Accident	13/04/2021 17:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BRADDELL ROAD SLIP ROAD JUNCTION TO TOA PAYOH LORONG 6
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBL9899C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN KWANG PHENG
NRIC No	SXXXX768F
Email Address	LOUIS1768@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-92393338
Alternative Phone No	(Home) +65-92393338

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Harrier
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA549432
Cover Note Number	-

DRIVER

Name of Driver	TAN KWANG PHENG
----------------	-----------------



NRIC No	SXXXX768F
Date Of Birth	02/07/1970
Occupation	Indoor
Date Of Driving Pass	05/01/1993
Driving experience	28 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92393338
Alt. Phone Number	(Home) +65-92393338
Email Address	LOUIS1768@YAHOO.COM.SG
Address	BLK 563 ANG MO KIO AVENUE 3 #08-3449
Address complement	-
Postcode	560563
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA3103G
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-91691741
Address	-

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


14/1/18
11:20am



Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Braddell Road entered into the slip road and stopped at the junction waiting for the front on moving traffic on Tao Payah Lorong 6 to clear before I could drive forward. Suddenly I heard a loud bang and came out of my vehicle and realise vehicle B has collided into the rear of my vehicle.

TP Claim other workshop.

**Please forward a copy of my efile report to my workshop Complete VMS Pte Ltd

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

17/4 @
1120AM


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





TAN KWANG PHENG
BLK 563 ANG MO KIO AVENUE, 3 #08-3449
SINGAPORE 560563

Attention : THE OWNER

Contact : 92393338

Estimate : ES007170

Date : 13/04/2021

Vehicle Num. : SBL9899C

Make/Model : TOYOTA HARRIER G GRADE-2018

Chassis/Eng# : JTEKB3GH80J002942/8ARZ136990

Accident Date : 13/04/2021

Claim No. :

Reference :

Policy No. :

*Not Authorized
11/12/21
Recovery After Paint
5-6 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER		1,495.00 ✓
2.	1	REAR BUMPER LOWER GARNISH		625.00 ✓
3.	2	REAR BUMPER BRACKET	123.50	247.00 ?
4.	6	REAR BUMPER CLIP	6.50	39.00 ✓
5.	2	REAR BUMPER SIDE RETAINER	102.70	205.40 ?
6.	2	REAR BUMPER REFLECTOR	83.20	166.40 x
7.	2	REAR BUMPER REFLECTOR CHROME GARNISH	85.00	170.00 ?
8.	1	REAR BUMPER SPONGE		168.00 ✓
9.	1	REAR BUMPER REINFORCEMENT		335.00 ?
10.	1	REAR END PANEL TOP GARNISH		478.30 ?
11.	2	REAR END PANEL TOP GARNISH CHROME PLATE	55.00	110.00 ?
12.	1	REAR END PANEL		1,006.40 ?
13.	1	SPARE TIRE PANEL		1,387.80 x
14.	1	TAIL GATE WEATHER STRIP		456.00 ?
15.	1	REAR EXHAUST SILENCER BOX		1,650.00 ?
16.	1	TAIL GATE		2,378.00 ✓
17.	2	TAIL GATE SHOCK ABSORBER	1,330.00	2,660.00 x
18.	1	TAIL GATE LOCK		975.00 ?
19.	1	TOYOTA LOGO		61.83 ✓
20.	1	HARRIER EMBLEM		77.90 ✓
21.	1	TURBO EMBLEM		98.00 ✓
22.	2	REAR W/SCREEN MOULDING	91.60	183.20 ✓
23.	4	REVERSE SENSOR HOLDER	35.00	140.00 ?
List TotalS\$:				15,113.23
25.00% Discount S\$:				3,778.31
				11,334.92
SPECIAL NETT ITEMS :				
1.	1	REAR W/SCREEN SEALANT		65.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...



TAN KWANG PHENG
BLK 563 ANG MO KIO AVENUE, 3 #08-3449
SINGAPORE 560563

Attention : THE OWNER

Contact : 92393338

Estimate : ES007170

Date : 13/04/2021
Vehicle Num. : SBL9899C
Make/Model : TOYOTA HARRIER G GRADE-2018
Chassis/Eng# : JTEKB3GH80J002942/8ARZ136990
Accident Date : 13/04/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REVERSE SENSOR	305.00	1,220.00
		Special Nett Total S\$:		1,285.00
		LABOUR :		
		RUST PROOFING TREATMENT		100.00
		TRANSFER TAILGATE COMPONENT TO NEW GATE		150.00
		SPRAY PAINT DAMAGED AREA AFFECTED		1,100.00
		REMOVE & REINSTALL REAR W/SCREEN GLASS		180.00
		TO CUT & CHANGE REAR END PANEL, SPARE TIRE PANEL, KNOCK AND STRAIGHTEN REAR END CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,500.00
		Labour Total S\$:		3,030.00

SingDollars : Fifteen Thousand Six Hundred Forty-Nine & Cents Ninety-Two Only

Total S\$: 15,649.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which
may be required after the work has begun



TAN KWANG PHENG
BLK 563 ANG MO KIO AVENUE, 3 #08-3449
SINGAPORE 560563

Attention : THE OWNER
Contact : 92393338

Estimate : ES007170

Date : 13/04/2021
Vehicle Num. : SBL9899C
Make/Model : TOYOTA HARRIER G GRADE-2018
Chassis/Eng# : JTEKB3GH80J002942/8ARZ136990
Accident Date : 13/04/2021
Claim No. :
Reference :
Policy No. :

Not Notched
11 Pm @ 8050h
Running After Paint
7 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|---|---|--------|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | REAR BUMPER | 397.60 | |
| 3. | 2 | REAR BUMPER LOWER GARNISH | | |
| 4. | 6 | REAR BUMPER BRACKET | | |
| 5. | 2 | REAR BUMPER CLIP | | |
| 6. | 2 | REAR BUMPER SIDE RETAINER | | |
| 7. | 2 | REAR BUMPER REFLECTOR | | |
| 8. | 1 | REAR BUMPER REFLECTOR CHROME GARNISH | | |
| 9. | 1 | REAR BUMPER SPONGE | | |
| 10. | 1 | REAR BUMPER REINFORCEMENT | | |
| 11. | 2 | REAR END PANEL TOP GARNISH | | |
| 12. | 1 | REAR END PANEL TOP GARNISH CHROME PLATE | | |
| 13. | 1 | REAR END PANEL | | |
| 14. | 1 | SPARE TIRE PANEL | | |
| 15. | 1 | TAIL GATE WEATHER STRIP | | |
| 16. | 1 | REAR EXHAUST SILENCER BOX | | |
| 17. | 2 | TAIL GATE | | |
| 18. | 1 | TAIL GATE SHOCK ABSORBER | | |
| 19. | 1 | TAIL GATE LOCK | | |
| 20. | 1 | TOYOTA LOGO | | |
| 21. | 1 | HARRIER EMBLEM | | |
| 22. | 2 | TURBO EMBLEM | | |
| 23. | 4 | REAR W/SCREEN MOULDING | | |
| | | REVERSE SENSOR HOLDER | | |

List TotalS\$:
25.00% Discount S\$:

Br/Na	1,495.00	
Na	625.00	
123.50	247.00	
6.50	39.00	
102.70	205.40	
83.20	166.40	
85.00	170.00	
Na	168.00	
Na	335.00	
Na	478.30	
55.00	110.00	
Na	1,006.40	
Na	1,387.80	
Na	456.00	
Na	1,650.00	
Na	2,378.00	
1,330.00	2,660.00	
Na	975.00	
Na	61.83	
Na	77.90	
Na	98.00	
91.60	183.20	
35.00	140.00	
	15,113.23	
	3,778.31	
	11,334.92	

- | | | |
|----|---|---|
| 1. | 1 | SPECIAL NETT ITEMS :
REAR W/SCREEN SEALANT |
|----|---|---|

Na 4050 65.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...



TAN KWANG PHENG
BLK 563 ANG MO KIO AVENUE, 3 #08-3449
SINGAPORE 560563

Attention : THE OWNER
Contact : 92393338

Estimate : ES007170

Date : 13/04/2021
Vehicle Num. : SBL9899C
Make/Model : TOYOTA HARRIER G GRADE-2018
Chassis/Eng# : JTEKB3GH80J002942/8ARZ136990
Accident Date : 13/04/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REVERSE SENSOR	305.00	1,220.00
		Special Nett Total S\$:		1,285.00
		LABOUR :		
		RUST PROOFING TREATMENT		100.00
		TRANSFER TAILGATE COMPONENT TO NEW GATE		150.00
		SPRAY PAINT DAMAGED AREA AFFECTED		1,100.00
		REMOVE & REINSTALL REAR W/SCREEN GLASS		180.00
		TO CUT & CHANGE REAR END PANEL, SPARE TIRE PANEL, KNOCK		
		AND STRAIGHTEN REAR END CHASSIS FRAME AND CHANGE ALL		
		NECESSARY PARTS		1,500.00
		Labour Total S\$:		3,030.00

SingDollars : Fifteen Thousand Six Hundred Forty-Nine & Cents Ninety-Two Only

19,509.12
Total S\$: 15,649.92
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



TAN KWANG PHENG
BLK 563 ANG MO KIO AVENUE, 3 #08-3449
SINGAPORE 560563

Attention : THE OWNER
Contact : 92393338

Supplementary Estimate : ES007172

Date : 17/04/2021
Vehicle Num. : SBL9899C
Make/Model : TOYOTA HARRIER G GRADE-2018
Chassis/Eng# : JTEKB3GH80J002942/8ARZ136990
Accident Date : 17/04/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR END PANEL ANTENNA	CM 96.00	✓
2.	1	SPARE TIRE LOCK/NUT	CM 55.00	✓
3.	1	STORAGE COMPARTMENT TRAY	DL 676.70	✓
4.	1	STORAGE COMPARTMENT INNER SPONGE	SM 194.50	X
5.	1	TOOL BOX L/H	DL 670.50	✓
6.	1	TOOL BOX R/H	MSM 474.20	✓
7.	1	REAR COMPARTMENT GARNISH L/H	DL 596.40	✓
8.	1	REAR COMPARTMENT GARNISH R/H	DL 517.80	✓
9.	1	REAR LOWER DAMPER	DL 1,343.10	✓
10.	2	BRACEKET TOWER BAR	215.30 R 430.60	X
11.	2	RETAINER ULTRASONIC	45.40 M 90.80	✓
List TotalS\$:				5,145.60
25.00% Discount S\$:				1,286.40
				3,859.20

SingDollars : Three Thousand Eight Hundred Fifty-Nine & Cents Twenty Only

Total S\$: 3,859.20

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun