

ASS. REC. BY:

OR

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1800102058

Claims No. 4671586177SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 56K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO BODY INJURED

27/04/21 Submit DAR; 2 repair days.

Date/Time, File Pass to?

☐

Preli. Report

1) 27/04 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Misc. Insp (\$

Report Format:

MER-DAR

Date/Time, File Return to?

2 Days

Vehicle No: 9KS 5757C

SAC	INC	Item	CONAC	QTY
1016	991533	Frt RH Door	Repair	
1017	991654	Frt RH Door Protector	MC	
1018	991601	Frt RH Door Hinge		
1019	991685	Frt RH Door Wing Mirror		
1020	991583	Frt RH Door Garnish	MC	
1021	991609	Frt RH Door Glass Outer Moulding		
1022	991588	Frt RH Door Glass Inner Moulding		
1023	991584	Frt RH Door Glass		
1024	991595	Frt RH Door Glass Regulator		
1025	991596	Frt RH Door Glass Regulator Motor		
1026	991662	Frt RH Door Rubber		
1027	991636	Frt RH Door Outer Handle		
1028	991607	Frt RH Door Inner Handle		
1029	991625	Frt RH Door Lock w/Key		
1030	991624	Frt RH Door Lock		
1031	991562	Frt RH Door Central Lock		
1032	991675	Frt RH Door Switch		
1033	991613	Frt RH Door Inner Trim Board		
1034	991568	Frt RH Door Checker		
1035	991575	Frt RH Door Felt		
1036	991688	Frt RH Door Wire Harness		
1037	991683	Frt RH Door Window Glass Pillar		
1038	991640	Frt RH Door Outer Pillar		
1039	991613	Frt RH Door Inner Pillar		
1040	991646	Frt RH Door Pillar Inner Garnish		
1041	990554	Centre Pillar RH		
1042	990543	Centre Inner Pillar RH		
1043	990515	Centre Pillar Upper Garnish RH		
1044	990565	Centre Pillar Lower Garnish RH		
1045	991670	Frt RH Door Step Garnish		
1046	994058	Rocker Panel RH		
1047	994049	Rocker Panel Inner Panel RH		
1048	994047	Rocker Panel Garnish RH		
1049	994055	Rocker Panel Outer Side Skirt RH		
1004	991300	Frt Bumper		
1006	991325	Frt Bumper Bracket		
1007	991462	Frt Bumper Side Retainer		
1008	991433	Frt Bumper Reinforcement		
1010	991468	Frt Bumper Sponge		
1011	991427	Frt Bumper Protector		
1014	991301	Frt Bumper Moulding		
1015	991407	Frt Bumper Lower Spoiler		
1030	991821	Frt RH Headlamp Assy		
1032	995089	Frt RH Side Lamp		
1105	995071	Frt RH Fender	Repair	
1107	991744	Frt RH Fender Lamp		
1108	991752	Frt RH Fender Protector	MC	

Assessor: _____

[illegible]