	210048411kg
Kenneth	SIGNMENT
Estimated Cost:  OD UTP/WS/TP RES/OD RES/EVA/INV/MV  To Inspect Vehicle No: at Workshop m/s  Trans Cab	Veh No: Sm X 6837A Yr Regn: C1 21  Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /  Truck / Trailer or  Make: Toy Privs c.c 1798
of	2/0
Insured:	Eng/No:
Claims No.  Claims No.  Claims No.  Claims No.  Claims No.  Consistent?: Yes or No  Est. Repairs:  Consistent?: Yes or No  Consum:  Consum:  Consistent?: Yes or No  Consum:  Consum:	C/No: JTDKB 3/EU 703.891426  Gen. Cond: 8606 / Fair / Poor / Burnt  Steering: Inorder / Jammed / Leaked / Burnt or  Brake: Inorder / Jammed / Leaked / Burnt or  Modi: NII / S/RIm / STD A/RIm or  Tyre Size: F: // S//S/IS  R:  BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /  TOYO / YOKO or  Fron! Rear  R/Bal. J mm R/Bal. J mm  L/Bal. J mm  D.O.A. / 3 / 4 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
2814 & H65-08- 1414.60 CRO	MB 12392.33, 90%)
1179/5 121/61	ays Of Repair:  esurvey No. of Trip:  Survey Fee:  Transportation:  Site insp (\$ ) _ \$ + RS \$!  Interview (\$ ) Fixe is  Tech Invs (\$ ) Others  Weekend (\$ )
	10TAL

Trans-cab Auto Services Pte Ltd  No. 2 Ang Mo Kio Street 63 Singapore 569111  Tel No.: 6287 6666 Fax No.: 6257 1330  CO./GST Reg. No. 201019626G  SMX6857A  Vehicle No.: Chassis No.:	LAD2104-006  NOT North eises  Resurry B4 paint  \$ 141460  SMX6857A  JTDKB3FU703091426
Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer: Date of Registration:	TOYOTA PRIUS <b>GEN 4</b> 13/04/2021 <b>ECICS</b> 26/01/2021 <b>LIST</b>
1 COVER, REAR BUMPER 1 REINFORCEMENT SUB-ASSY, REAR BUMPER 1 COVER, REAR BUMPER, LOWER 1 GUARD, REAR BUMPER, CENTER 1 RETAINER, REAR BUMPER SIDE, LH 1 RETAINER, REAR BUMPER SIDE, RH 1 REFLECTOR ASSY, REFLEX, LH 1 REFLECTOR ASSY, REFLEX, RH 1 COVER, FLOOR UNDER, NO.1 LH 1 COVER, FLOOR UNDER, NO.2 RH 1 COVER, REAR FLOOR CTR 1 PANEL SUB-ASSY, BODY LOWER BACK	\$ Bu 485.60 \$ By 332.70 x \$ 22.00 x \$ 22.00 x \$ 374.50 \$ 132.60 x \$ 139.00 x \$ 39.00 x \$ 175.10 x \$ 241.90 x \$ 651.00 x  TOTAL \$ 2,855.90 \$ 713.98 \$ 2,141.93
Special Nett  1SET PARKING AID  1SET REAR BUMPER CLIP  1 REAR BUMPER PROTECTOR  2 SEAM SEALANT  1SET REAR BUMPER RETAINER CLIP  1 END PANEL TRIM CLIP	\$ 700.00 X \$ 700.00 X \$ 180.00 X \$ 180.00 X \$ 250.00 X \$ 85.00 X TOTAL \$ 1,375.00 TOTAL PARTS \$ 3,516.93

**LABOUR** 

<b>Trans-cab Auto Services Pte Ltd</b> No. 2 Ang Mo Kio Street 63 Singapore 569111  Tel No. : 6287 6666 Fax No. : 6257 1330  CO./GST Reg. No. 201019626G	LAD2104-006
SMX6857A	
To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$ N~ 300.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ ~~ 380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$ 2,200.00 <i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$ <b>4</b> 380.00 <b>X</b>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$ ∠ 180.00
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$ <b>4</b> 480.00 <b>X</b>
To transfer of Fender fittings, attachments and perform water seepage test.	\$ 5 480.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$ ∽ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ <b>5</b> 380.00 <b>X</b>
To check steering geometry and computer wheel alignment	\$ <b>5</b> 220.00 X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$ <b>5</b> 250.00 <b>X</b>
Towing Fees	\$ ∽ 150.00 X
Putty And Spray Painting Of The Affected Portion.	\$ 2,200.00 220/

<b>Trans-cab Auto Services Pte Ltd</b> No. 2 Ang Mo Kio Street 63 Singapore 569111	LAD2104-006	
Tel No. : 6287 6666 Fax No. : 6257 1330		
CO./GST Reg. No. 201019626G		
SMX6857A		
To reinstall rear bumper parking sensor.	\$ 170.00	50%
To Check Electrical Lighting Concerned.	\$ N 170.00	X
To transfer of luggage floor panel fittings, attachment and		
perform water seepage test.	\$ <b>4</b> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$ <b>4</b> 220.00	X
To replace, refix and top up coolant for radiator	\$ <b>5</b> 170.00	X
To lift-up / out engine with gear box and refit.	\$ <b>4</b> 440.00	X
To remove and refit radiator support cross-member and other		
necessary items to enable bodywork repair.	\$ <b>5</b> 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check		
and reset vehicle warning indicators.	\$ <b>4</b> 380.00	X
TOTAL	\$ 10,290.00	
Over All Total	\$ 13,806.93	
(PART-BY-PART) Repair Days	25-DAYS 2day,	

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ST0R214E0001 / Trans Leasing Pte Ltd ENTRY DATE & TIME: 14/04/2021 11:19 (SGT) SUBMITTED BY: Tay Xin Er Amanda VERSION: 1 (14/04/2021 11:19 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
   By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 14/04/2021 11:19 (SGT) Date of Accident 13/04/2021 20:30 (SGT) Exact Location of Accident Singapore Additional Location Information ANG MO KIO AVE 3 X SERANGOON NORTH AVE 1 Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMX6857A

## INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner Trans Leasing Pte Ltd Company Reg No 2XXXXX575K **Email Address** claims@transcab.com.sg Mobile Phone No (Phone) +65-62876666 Alternative Phone No (Office) +65-62876666

#### VEHICLE PARTICULARS

Manufacturer Toyota Model Prius Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private hire Transmission Auto CC 1800

# INSURANCE COMPANY

Name of Insurance Company Etiqa Insurance Pte Ltd Type of Coverage ThirdParty Fleet Policy Policy Number M0015914 Cover Note Number

### DRIVER

Name of Driver LIM CHOK YONG NRIC No SXXXX108C



02/04/1963 Occupation Outdoor Date Of Driving Pass 15/05/2012 Driving experience 8 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-90828383 Alt. Phone Number **Email Address** alimcy@hotmail.com Address **BLK 181 STIRLING ROAD** Address complement #02-216 Postcode 140181 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other material or property damaged? Yes

PASSENGER 1

Date Of Birth

Name JARRED THAM Gender Male

DETAILS OF POLICE ACTION

Number of Passengers (Including Driver)

soliciting/offering accident claims assistance?

Has the driver been approached by unknown person(s)

Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom?

#### CIRCUMSTANCES OF ACCIDENT

ON 13/04/2021 AT ABOUT 2030HRS, I WAS STATIONARY ON THE THIRD LANE OF ANG MO KIO AVENUE 3 JUNCTION TO SERANGOON NORTH AVE 1 DUE TO RED TRAFFIC LIGHT. I SUDDENLY FELT AN IMPACT FROM THE REAR OF MY VEHICLE. VEHICLE B(SMN7559G) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

No

# ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident FILE SIZE TOO BIG Was there any audio recorded?

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMN7559G Vehicle Manufacturer Vehicle Model



 Vehicle Variant

 Vehicle Colour

 Vehicle Category
 Private car

 Name of Driver

 Contact Number

 Address

 Address complement

 Postcode

 Insurance Company Name

 Nature Of Damage

 Details of property damaged in accident

 No. Of Passenger (Including Driver)

# INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person

Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?

LIM CHOK YONG
SMX 6857A
Were SMX 6857A
Yes
No

### WITNESS DETAILS

#### WITNESS 1

 Name
 JARRED THAM

 Phone
 (Phone) +65-91006405

 Email

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
- lunderstand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


X:

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Zhuwli Witnessed by Reporting Centre Personnel

Sketch Plan



			- manne	
Keli	or to GIA Repo	rt		
	,			
			V	
		***************************************	*************************************	
irs are true in eve	ery respect.			
	XI -			
	N		7	1
				we.
		Refer to GIA Repo	Refer to Q1# Report.	

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	575K	
Vehicle No.:	SMX6857A	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	14 Apr 2021	
Vehicle Make:	TOYOTA	
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)	
Primary Colour:	Silver	
Manufacturing Year:	2020	
Engine No.:	2ZR2G79618	
Chassis No.:	JTDKB3FU703091426	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$26,807.00	
Original Registration Date:	26 Jan 2021	
First Registration Date:	26 Jan 2021	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$14,530.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	25 Jan 2031	
PARF Rebate Amount: Intended COE Rebate Details	\$10,897.00	
COE Expiry Date:	25 Jan 2031	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$30,890.00	
COE Rebate Amount:	\$24,712.00	
Total Rebate Amount:	\$35,609.00	

The information contained herein is correct as at 14 Apr 2021