



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21004845/Avf3n2 Date: 07/09/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGK 8880H	Veh. Inspected	SFT 280G	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009867/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	19/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2050402R339097	Colour	GREY	
Odometer	70245 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/04/2021	Inspection Date	19/04/2021	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	