



**SINGAPORE
POLICE FORCE**



T/20210420/2027

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 4

Report No. T/20210420/2027

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/04/2021 10:51		Vide Report No.:		Station Diary No.: 50	
Informant's Particulars					
Name of Informant: SARKER MD MAHMUDUL			Address: C/O APT BLK 548a Macpherson Road SINGAPORE 368227		
ID Type / ID No.: FIN NO / G8528177T			Contact No.: Home/Office: Mobile: 82697282		
Nationality: BANGLADESHI			Email:		
Sex: Male	Age: 22	Date of Birth: 27/12/1998	Type of Informant: Driver		
Race: Bangladeshi			Language:		Institution / School Name:
Occupation: ELECTRICAL			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 16/04/2021 07:30	Type of Location: Straight Road
Location: JALAN BAHAR				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE725S	Lorry	NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	Silver	Slightly Damaged	8
SGL6548B	Car	CHEVROLET	AVEO5 HB AT	Red	Seriously Damaged	0
SMQ2776M	Car	HONDA	SHUTTLE 1.5G CVT SENSING	Blue	Slightly Damaged	0



Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20210420/2027

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SARKER MD MAHMUDUL	ID No.	G8528177T
Related Vehicle	GBE725S (Lorry)	Contact No.	82697282
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	THIRUNAGARASU S/O TANGAVELLU	ID No.	S7004809D
Related Vehicle	SGL6548B (Car)	Contact No.	81804094
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	HO HAI HWA	ID No.	S7821469D
Related Vehicle	SMQ2776M (Car)	Contact No.	91518994
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/04/2021 at about 0730hrs, I was driving my lorry (Vehicle registration number: GBE725S) along Jalan Bahar. It was a straight road and I was driving on the first lane of the two lane road. There was a lot of traffic and it was also raining. The car (red colour) (Vehicle registration number: SGL6548B) in front of me suddenly braked to a stop. I tried to brake however, my vehicle could not stop in time. My vehicle then collided onto the car in front of me and that car then collided onto another car (dark blue colour) (Vehicle registration number: SMQ2776M). It was a chain collision involving three vehicles.

After the collision, the drivers of the other two vehicles and myself went to the side of the road to



**SINGAPORE
POLICE FORCE**



T/20210420/2027

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 4

Report No. T/20210420/2027

CONTINUATION OF REPORT

exchange particulars. The particulars of the driver from the red colour vehicle is as follows: Name: Thirunaugasu S/O Tangavellu, NRIC: S7004809D, HP: 81804094. The particulars of the driver from the black colour vehicle is as follows: Name: Ho Hai Hwa, NRIC: S7821469D, HP: 91518994. All the vehicles were damages. The front of my lorry had dents, The front right headlight was broken and the front bumper was also damaged. The red colour car had damages to the back and the front. The back had dents, the front boot was broken, both the front headlights were damaged, the front bumper was also damaged and there were also multiple scratches on the front of the car. The dark blue colour car had damages to the rear of the car. There were scratches and dents.

No one was injured during the incident. Ambulance and Traffic Police were not at scene. This is second time I have been involved in an accident



SINGAPORE
POLICE FORCE



T/20210420/2027

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

4 of 4

Report No. T/20210420/2027

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

SC2 RAHIK RAHMAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476229

Signature Of Informant:

Date/Time:

20/04/2021 10:51

Classification Of Case:

Authentication Stamp

NP168

