

SLA82101C.

Honda Vezel

TRAXA
Vezon

RU111144T.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rear RH Door

Dented

1120.40

Rear RH Door Weatherstripe.

3/4
1/4

142.10 X

Rear RH Door Lock.

296.60 X

Rear RH Fender Wheel Arc Garnish

1/4

173.20.

Rear RH Fender Wheel Arc Garnish Clips

1/4

20(SN)

Rear RH Wheel Rim.

1/4

600(SN) X

Panel Beating.

~~600~~ 200

Spray Painting.

~~600~~ 250

Wiring.

~~50~~ 30.

To perform wheel alignment

150 X

To transfer rear door fittings.

~~150~~ 80.

Wist: 1293.60

Len 20%: 1034.88

S-N: 20

Labour: 560

Total: 1614.88

4/5: 1.2K.

03Days