



Service Requests

Messages

Claims



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### General Details

Involving	TPVD HONDA VEZEL (SLA8210K)
Date of Loss	15 April 2021
Time of Loss	19:10
Loss Description	SHC8508P (INSD) LANE CHANGE HIT SLA8210K (TP)
Comment	<input type="text"/>

### Workshop Details

Total Rebate  
Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work  
completion \*

20



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration# SLA8210K

Registration State

SINGAPORE

Mileage

160094

Purchase Date

DD/MM/YYYY



Registration Date \*

17/03/2016



Age of Vehicle

5

CATEGORY

POLICY  
INFORMATION

ASSESSMENT INFORMATION

Manufacturing  
Year

2015

## Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY  
INFORMATION





Driver Name

TAN HONG  
YEOW

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD HONDA	<input type="text" value="HONDA"/>
Model	VEZEL	<input type="text" value="VEZEL 1.5X A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="RU11111444"/>
Engine No		<input type="text" value="L15B4031449"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	14 March 1980	<input type="text" value="DD/MM/YYYY"/> 
Age	41	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	XXXXX561H	<input type="text"/>



Service Requests

Messages

Claims



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

21/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake  
(Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

215/55R16

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Spare wheel

Rear Tyre Size

215/55R16

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



Service Requests

Messages

Claims



# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="20"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<div><div>Yes</div><div>No</div></div>	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>			

A  
X  
A

Save



Service Requests

Messages

Claims





Assessment Details







- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Parts

Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR RH DOOR	Dented	0	1120.4	No	0	20	0	0	896.32
	0	1		REAR RH DOOR WEATHERSTRIPE	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR RH DOOR LOCK	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR RH FENDER WHEEL ARC GARNISH	Cut	0	173.2	No	0	20	0	0	138.56

Labour

Add		Approve		Deny		Submit All				
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		PANEL BEATING	0	200	0	0	Reviewing		
	0		SPRAY PAINTING	0	250	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		WIRING	0	30	0	0	Reviewing		
	0		TO PERFORM WHEEL ALIGNMENT	0	0	0	0	Deny		
	0		TO TRANSFER REAR DOOR FITTINGS	0	80	0	0	Reviewing		



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

## Summary

Add

Approve

Deny

Submit All

EDIT

SR  
NO

NAME

ACTION

ESTIMATED  
AMOUNT

ADJUSTED  
AMOUNT

COMMENT

REMOVE



0

DAYS OF  
REPAIR :  
3 DAYS

Reviewing

0

0



0

REAR RH  
FENDER  
WHEEL  
ARC  
GARNISH  
CLIPS



Reviewing

0

20

NECESSARY



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR RH WHEEL RIM	Deny	0	0	NOT NECESSARY	

[Service Requests](#)[Messages](#)[Claims](#)

# Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$1,614.88
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review





Assessment Details

General & Workshop Details

Vehicle & Driver Details



Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	1200		



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$1,200.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
----------	----------	----------

Miscellaneous		
---------------	--	--

Submit for Review