



Service Requests

Messages

Claims



Service Request Details

Claim	S1M0388B
Reference	CS/ASM21004870/Avce2
Loss Date	15 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	19 Apr 2021 8:33:11 AM
Request Date	19 April 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SLA8210K
Vehicle	
Registration #	
Make	TPVD HONDA
Model	VEZEL

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

YU Dominic Yishan

dominic.yuys@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2103933.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	8 June 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP LOD (DUPLICATE)TAN HONG YEOW.msg.msg	Legal	Others	VISHNU BATHAM Shekhar	31 May 2021
 LKKPhotosIn4.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2021
 IA.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2021
 LKKPhotosIn RESURVEY.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2021
 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	19 April 2021