REF: SMO/210048801kg

ASSIGNMENT

Pin 1225/ Vibani 11,17

A/2021

nttps://vacsweb.smrt.com.sg/Estimation.aspx



Case Details

Case Reference Number: TAX/04/21/2050
Type of Repair: Accident Repair
Vehicle Registration Number: SHB1235C
Company Type: SMRT Taxis Pte Ltd
Estimation ID: EST-14622-ID
Assigned By: Taxi Claims Manager Team

Type of Repair : Accident Repair Vehicle Registration Number : SHB1235C

Insurance Company Name: Sompo Insurance Singapore Pte. Ltd Accident Date and Time: 18/04/2021 05:20 AM Vehicle Age(In Months): 41

Documents / Photographs

View Documents / Photographs

Total Documents: 0

NOT MANIN Prenny Afer Paint

Estimation Details

Spare Part's Cost Detail

| SMRT Recommendation | | | | | | | | | | | Surveyor Approval | | | |
|--------------------------|-----------------|---------|--------------------|------------------------------|-----|----------------------------------|-------------------|--------|--------------------|--------------------|----------------------|--------------------------------|----------------|---------|
| BOM Type | Costing Type | Portion | Material Number | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | COVER, FR BUMPER | 1 | 495.50 | 495.50 | 25.00 | 371.63 | Bn | 1 | 371.63 | Replace Y | |
| One Time Key In | Main | | | SUPPORT, FR BUMPER RH | 1 | 76.90 | 76.90 | 25.00 | 57.68 | Replace | 1 | 57.68 | Replace V | |
| One Time Key In | Main | | | SUPPORT, FR BUMPER LH | 1 | 82.30 | 82.30 | 25.00 | 61.72 | Replace | 0 | 0 | Not Giv∈ ✓ | |
| One Time Key In | Main | | | COVER, FR BUMPER RH | 1 | 28.10 | 28.10 | 25.00 | 21.08 | Replace | 0 | 0 | Not Give 🕶 | |
| One Time Key In | Main | | | REINFORCEMENT FRONT UPPER | 1 | 691.10 | 691.10 | 25.00 | 518.33 | Replace | 1 | 0 | Repair 🕶 | |
| One Time Key In | Main | | | ABSORBER, FR BUMPER | 1 | 70.30 | 70.30 | 25.00 | 52.72 | Replace | 0 | 0 | Check • | Sux |
| One Time Key In | Main | | | EXTENSION SUB- ASSY, LH | 1 | 116.30 | 116.30 | 25.00 | 87.22 | Replace | 0 | 0 | Not Give ✓ | |
| One Time Key In | Main | | | EXTENSION SUB- ASSY, RH | 1 | 116.30 | 116.30 | 25.00 | 87.22 | Replace | 0 | 0 | Not Give ~ | |
| One Time Key In | Main | | | REINFORCEMENT FRONT LOWER | 1 | 238.50 | 238.50 | 25.00 | 178.88 | Replace | 0 | 0 | Not Give v | |
| One Time Key In | Main | | | ABSORBER, FR BUMPER LOWER | 1 | 117.00 | 117.00 | 25.00 | 87.75 | Replace | 0 | 0 | Check | su X |

Surveyor Total 3,374.36 Total Spare Part Cost 16,820.38 Lump Sum Dis (%) 20 Lump Sum Discount (%) 20.00 Final Sur Total 2,699.49 Final Spare Part Cost 13,456.30