

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305464503 Via Fax : EMAIL
Date : 19-4-21 Your Insured : YN 3961L
Time of Fax : _____ Date of Acc : 17-4-21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

07066 Z

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE
Vehicle No.: SHD7066Z

Make : HYUNDAI

Model : IONIQ

DOA : 17.04.21

Date : 19.04.21

Insurance: AIG

MVA : JUMANI

Qty	Parts Description / Labour	Qty	Unit Price	Amount
1	FRT LH DOOR ASSY	1		\$1,106.00
2	REAR LH DOOR ASSY	1		\$35.60
3	FRT DOOR OUTER HANDLE	1		\$22.00
4	FRT DOOR OUTER HANDLE COVER	1		\$33.20
SUB TOTAL				\$1,196.80
LESS 20%				\$239.36
DISCOUNTED TOTAL				\$957.44
	FRT DOOR COMFORTDELGRO LOGO	1		\$75.00
	REAR APPS LOGO	1		\$85.00
				\$160.00
Labour Charge				
	PANEL BEATING	2		\$800.00
	SPRAYPAINT			\$600.00
	WIRING			\$50.00
	TRANSFER DOOR PARTS			\$240.00
TOTAL LABOUR				\$1,690.00
ESTIMATE TOTAL				\$2,807.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305464563


OWNER	REGN NO: SHD7066Z	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OWNER NO. 7010045	MODEL IONIQ(G3)	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	YR OF MANU. 25.02.2021	DATE/TIME IN 19.04.2021 10:30
TESS Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVLU192894	TARGET DATE
(R) 65508755 (O)		COMPLETION DATE/TIME:
(P)		
DUPLICATE CARD NO.		

JOB DESCRIPTION

Accident Date: 17.04.2021

ATURE: 3P 17.4.2021

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

do.:

SHD7066Z

JU AIG

Vehicle No.:

SHD7066Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard