

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT21001325	Page	1
Registration No	: SBY1100H	Date	: 17. Apr 2021		
Chassis No	: JHMRU1810JX202353	Customer No.	: WZC008		
Model	: HRV DX-SIN CVT YM 2018	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: CHAN CHEE OONG	Engine No	: L15B5672358		
Ins Policy No.	:	Date Time	: 17. Apr 2021 1:11:55 PM		
Date of Accident	: 16/4/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHAN CHEE OONG OWNER INSURER: TOKIO MARINE ACC DATE: 16/04/2021 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING INSURANCE TP VEH: SJU8627K						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
73226-SZW-000	DAMPERSTD 5X5	1	9.10	5	8.64	0.60	9.24
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
76711-T6A-003	CAPPIVOT	1	5.20	5	4.94	0.35	5.29
91501-S70-003	FASTENER BW/SHIELD	4	5.30	5	20.14	1.41	21.55
91502-S70-003	FASTENER B	2	5.50	5	10.45	0.73	11.18
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	7.22	0.51	7.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP	1	912.60	5	866.97	60.69	927.66
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	145.10	5	137.84	9.65	147.49
74440-T7A-003	WEATHERSTRIPTAILGATE	1	105.20	5	99.94	7.00	106.94
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY	1	174.00	5	165.30	11.57	176.87
75722-T7W-A01	EMBLEMRR.	1	15.20	5	14.44	1.01	15.45
75725-T8N-T00	EMBLEM, RR. I-VTEC	1	16.60	5	15.77	1.10	16.87
75701-T4G-000	EMBLEM	1	25.80	5	24.51	1.72	26.23
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
04715-T7A-900ZZ	FACE, RR. BUMPER	1	492.50	5	467.87	32.75	500.62
91505-TM8-003	CLIP, BUMPER	8	2.30	5	17.48	1.22	18.70
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	178.50	5	169.57	11.87	181.44

Printed on 17/4/2021 2:07:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SBY1100H

Chassis No : JHMRU1810JX202353

Model : HRV DX-SIN CVT YM 2018

Owner's Name : CHAN CHEE OONG

Ins Policy No. :

Date of Accident : 16/4/2021

Document No. : SQT21001325

Date : 17. Apr 2021

Customer No. : WZC008

Svc Advisor : RUEBEN THOMAS

Engine No : L15B5672358

Date | Time : 17. Apr 2021 1:11:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
33505-T7A-J01	REFLECTOR ASSY.RR.	1	178.50	5	169.57	11.87	181.44
71598-T7A-J00	SPACER,L.RR.BPR S	1	18.00	5	17.10	1.20	18.30
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	18.00	5	17.10	1.20	18.30
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
74940-TZ5-A01	BUZZER ASSYSMART	1	64.50	5	61.27	4.29	65.56
38387-TZ5-A01	ANTENNA ASSYL.F.	1	63.20	5	60.04	4.20	64.24
66100-T7A-300ZZ	PANEL COMPRR.	1	397.90	5	378.00	26.46	404.46
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	46.80	5	44.46	3.11	47.57
04711-T7A-J00ZZ	FACE,FR.BUMPER	1	507.10	5	481.74	33.72	515.46
91505-TM8-003	CLIP,BUMPER	22	2.30	5	48.07	3.36	51.43
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE	1	11.70	5	11.11	0.78	11.89
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE	1	11.70	5	11.11	0.78	11.89
71121-T7A-G01	BASE,FR.GRILLE	1	233.10	5	221.44	15.50	236.94
71122-T7A-J01	MOLDING,FR.GRILLE UPPER	1	227.00	5	215.65	15.10	230.75
75700-T5A-000	EMBLEM H	1	17.20	5	16.34	1.14	17.48
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
Sum Item					4268.72	298.81	4,567.53
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50

Printed on 17/4/2021 2:07:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT21001325	Page	3
	3 ANSON ROAD #16-00	Date	: 17. Apr 2021		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SBY1100H	Engine No	: L15B5672358		
Chassis No	: JHMRU1810JX202353	Date Time	: 17. Apr 2021 1:11:55 PM		
Model	: HRV DX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: CHAN CHEE OONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/4/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	3000.00		3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00		2800.00	196.00	2996.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1500.00		1500.00	105.00	1605.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00		1200.00	84.00	1284.00
Sum Labor					12210.00	854.70	13,064.70

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 16,478.72 1,153.51 **17,632.23**
Total (Inclusive of GST) **17,632.23**

Printed on 17/4/2021 2:07:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (Incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/04/2021 09:35 (SGT)
Date of Accident	16/04/2021 07:45 (SGT)
Exact Location of Accident	Near TPE, Halus Bridge, Singapore
Additional Location Information	TPE TOWARDS PASIR RIS (L/POST 377F)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBY1100H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHAN CHEE OONG
NRIC No	SXXXX505D
Email Address	echansg@gmail.com
Mobile Phone No	(Phone) +65-96793396
Alternative Phone No	(Home) +65-96793396

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MS012650
Cover Note Number	-

DRIVER

Name of Driver	CHAN CHEE OONG
NRIC No	SXXXX505D

Date Of Birth	15/07/1957
Occupation	Indoor
Date Of Driving Pass	10/08/1979
Driving experience	41 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96793396
Alt. Phone Number	(Home) +65-96793396
Email Address	echansg@gmail.com
Address	734 UPPER CHANGI ROAD EAST
Address complement	#01-11
Postcode	486862
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	7
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	JINGYI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Kampong Ubi Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18007479999
Alt. Police Station Phone No	(Fax) +65-67453410
Police Station Address	Blk 9 Eunos Crescent #01-2687 Singapore 400009
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK7707L
Vehicle Manufacturer	Honda

Vehicle Model	Vezel
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJU8627K
Vehicle Manufacturer	Toyota
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	NASIR BIN GHANI
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKU146Y
Vehicle Manufacturer	Nissan
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SJH1808U
Vehicle Manufacturer	Honda
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	

Details of property damaged in accident
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number	SMV6438L
Vehicle Manufacturer	Toyota
Vehicle Model	Sienta
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number	SGV4156J
Vehicle Manufacturer	Toyota
Vehicle Model	Vios
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

Vehicle

Number: SBY 110 H

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** - I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/initial packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

16/4/2021
11:58pm


Driver's Signature (if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Vehicle Number: SBY 1100 H.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

16/11/2021
11:55 pm

Driver's Signature (if driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
(Name)
RUC/FIN No.: