

VEHICLE INSPECTION FORM

OFFICIAL INSPECTION

No:

SM90989666SM1

Vehicle No:	GBG9738K	Registration Date:	06/12/2017
Make & Model:	MERCEDES B/CITAN 109 CDI	Road Tax Expiry Date:	05/12/2020
Engine No:	K9KE628D403982	Inspection Date/Time:	09/04/2021 11:02
Chassis No:	WDF4156052U221537	Location:	Sin Ming
IU No:	1042984129	Mileage:	
Test No:	1	Lane No:	1

Overall Result	Above Carriage	Noise *	Sideslip/Wheel-alignment	Brake	Head-Light	Under-Carriage	Speed * Limiter	Petrol * Emission	Diesel * Smoke	Taxi-Meter	Aircon Temp.
FAIL	FAIL	PASS	FAIL	PASS	FAIL	PASS			PASS		

Items	Status	Remarks
Above-carriage		
Head Lamps	Fail	Damaged lens cover
Bumper	Fail	Dented
CDST Power result : Passed CDST Smoke result : Passed		
NB: Please produce this form for REPEAT INSPECTION		
I have witnessed that the "Vehicle Under Inspection" sticker was pasted on the vehicle (for commercial vehicles only)		
Name:	I/C No:	Signature:

Legend : P - Pass F - Fail, Repeat inspection required CP - Pass with observation, No repeat inspection required (Repair soonest possible)

VICOM (Sin Ming) 385 Sin Ming Drive Singapore 575718 Tel: 6458 4555	VICOM (Changi) 20 Changi North Crescent Singapore 499613 Tel: 6545 4808	VICOM (Bukit Batok) 511 Bt Batok Street 23 Singapore 659545 Tel: 6567 7111	VICOM (Yishun) 501 Yishun Ind. Park A Singapore 768732 Tel: 6755 9028	VICOM (Kaki Bukit) 23 Kaki Bukit Ave 4 Singapore 415933 Tel: 6749 5422
---	---	--	---	--

REV. 10

GBG9738K OFFICIAL-Inspection 09/Apr 10:57.30 - 11:02.42
INSPECTORS : L/76211 P/02040 C/76206

*A: OUT 10.0 m/km

	WEIGHT(kg)	R-BR(kg)	L-BR(kg)	SUM(%)	DIFF(%)	DRAG(%)
FB1:	970	334	317	67.1	1.7	2.7
RB1:	600	214	216	71.6	0.3	2.8
RP1:	600	140	155	49.1		2.8
ALL:				68.8		

	Luminous(X100cd)	U/D(cm/10m)	L/R(cm/10m)
LH:	310	D 9.2	L 9.7
*RH:	* 0	U 0.0	R 0.0

DS:	Min Power required	29.0 KW	100% Engine Sp at Max P.	2438 RPM	2 HSU
	Corr. Max Power Measured	40.1 KW	90% Engine Sp at Max P.	2327 RPM	1 HSU
	Velocity Maximum Power	50.7 Kph	80% Engine Sp at Max P.	2050 RPM	0 HSU
SL:	61 db	0 RPM			