

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SME 43452
 at Workshop m/s: VOLKSWAGEN
 of 247, ALEXANDRA RD
 Insured: AH
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 75K
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SMG 43452 Yr Regn: 2018 / SEP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: SKODA OCTAVIA 1.0TSI AMB c.c 999
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 47089 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: TMBBP7NE4J0329934
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEKEN
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/04/21 D.O.I. 23/04/21
 Survey held at VOLKSWAGEN
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
O/S FRT
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit - 40K</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) _____
 Date/Time, File Return to?
 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

____ S + RS, ____ SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JOSHUA
POH ENG HENG
566 PASIR RIS STREET 51
#10-114
Singapore 510566

Document no.
Document date 20-04-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021015085/ 1
Job order date 19-04-2021
Service Advisor TIOW CHUAN CHEE

License plate SME4345Z	Model code 5E33BD	First registration 28-09-2018	VIN TMBBP7NE4J0329934	Model Octavia Ambition 1.0 I TSI 85kW DSG	Mileage 45,333
---------------------------	----------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5E0807221N	Cover For FRT BUMPER <i>3scd</i>	1	pcs.	1,371.14	#1	1,371.14	1,467.12
5E0807724A	Support Pa BUMPER INNER BRACKET RH <i>3?</i>	1	pcs.	43.78	#1	43.78	46.84
5E0807184A	Guide Piec RHS BUMPER SIDE BRACKET <i>3?</i>	1	pcs.	34.59	#1	34.59	37.01
5E0919485G	Sensor bracket <i>nc</i>	1	pcs.	12.93	#1	12.93	13.84
5E0919486G	Sensor bracket <i>nc</i>	1	pcs.	12.93	#1	12.93	13.84
5E0919485F	Sensor bracket <i>nc</i>	1	pcs.	12.93	#1	12.93	13.84
5E0919486F	Sensor bracket <i>nc</i>	1	pcs.	12.93	#1	12.93	13.84
D 180KU2A1	2k-Plastic Adhesive <i>nc</i>	1	pcs.	78.91	#1	78.91	84.43
D 822150A1	Bonding Agent For Plastic <i>nc</i>	1	pcs.	62.81	#1	62.81	67.21
5E2941016C	Halogen He H/LAMP RH <i>3scd</i>	1	pcs.	959.00	#1	959.00	1,026.13
5E0807682F 9B9	Cover For RHS FOG LAMP LOWER GRILLE <i>3?</i>	1	pcs.	48.36	#1	48.36	51.75
5E0941700F	Halogen Fo FOG LAMP RH <i>3?</i>	1	pcs.	263.62	#1	263.62	282.07
5E0821106C	Fender RH <i>3bt</i>	1	pcs.	616.26	#1	616.26	659.40
5E0821142A	Fender - B FENDER BRACKET RH <i>3?</i>	1	pcs.	98.92	#1	98.92	105.84
N 90959602	Rivitted Cap Nut <i>nc</i>	4	pcs.	2.23	#1	8.92	9.54
5E0809958D	Wheelhouse RHS FENDER LINER <i>3?</i>	1	pcs.	156.77	#1	156.77	167.74
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	4	pcs.	800.00	#1	3,200.00	3,424.04
	AIG DIRECT SETTLEMENT DOA: 19/04/2021 TP VEH: GBK8166X SURVEY BY:						

Quotation valid till 26-04-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,514.80	7%	719.24	10,274.80	10,994.04
Total	760.00	9,514.80		719.24	10,274.80	10,994.04

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
JOSHUA
POH ENG HENG
566 PASIR RIS STREET 51
#10-114
Singapore 510566

Document no.
Document date 20-04-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021015085/ 1
Job order date 19-04-2021
Service Advisor TIOW CHUAN CHEE

License plate SME4345Z	Model code 5E33BD	First registration 28-09-2018	VIN TMBBP7NE4J0329934	Model Octavia Ambition 1.0 TSI 85kW DSG	Mileage 45,333
---------------------------	----------------------	----------------------------------	--------------------------	--	-------------------

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Hp 90010068
4 days

23/04/21 @ 1145

Resurvey before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/04/2021 17:20 (SGT)
Date of Accident 19/04/2021 11:00 (SGT)
Exact Location of Accident St 51, Singapore
Additional Location Information OPENSOURCE CARPARK IN FRONT BLK 566/564
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME4345Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner JOSHUA POH ENG HENG
NRIC No SXXXX243F
Email Address pohjoshua@gmail.com
Mobile Phone No (Phone) +65-96836850
Alternative Phone No (Home) +65-96836850

VEHICLE PARTICULARS

Manufacturer Skoda
Model Octavia
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 999

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number -
Cover Note Number -

DRIVER

Name of Driver JOSHUA POH ENG HENG
NRIC No SXXXX243F

Date of Birth	09/11/1964
Occupation	Indoor
Date of Driving Pass	02/01/1985
Driving experience	36 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96836850
Alt. Phone Number	(Home) +65-96836850
Email Address	pohjoshua@gmail.com
Address	APT BLK 566 PASIR RIS STREET 51
Address complement	#10-114
Postcode	510566
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK8166X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Code
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
AIG Asia Pacific Insurance Pte. Ltd.
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Steven Chee
 Insurance Advisor
 Tel: 6305 7299 Ext: 511
 HP: 8511 2203
 Fax: 6285 8620

 3:55pm
 19/4/21
 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Date - 19/4/21

Time - 11 am (Discovered)

Location - Carpark at Pasir Ris St. 51 Infront of Blocks 566/564

When I went to my car this morning, I found my car is not in proper position. It was shifted slightly to the left. Upon inspection, I found my left ~~the~~ Right bumper was damaged with orange paint marks.

There was a note left on my wiper by someone who said he knocked my car and ask me to contact him.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature]
 19/4/21 3:55pm
 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
 Steven Chee
 Insurance Advisor
 Tel: 6305 7299 Ext: 511
 HP: 8511 2203
 Fax: 6285 8620

Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 243F

Vehicle No.: SME4345Z

Vehicle to be Exported: No

Intended Deregistration Date: 26 Apr 2021

Vehicle Make: SKODA

Vehicle Model: OCTAVIA 1.0 TSI AMBITION (A)

Primary Colour: Grey

Manufacturing Year: 2018

Engine No.: CHZA04848

Chassis No.: TMBBP7NE4J0329934

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$17,878.00

Original Registration Date: 28 Sep 2018

First Registration Date: 28 Sep 2018

Transfer Count: 0

Actual ARF Paid: \$17,878.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Sep 2028

PARF Rebate Amount: \$13,408.00

COE Expiry Date: 27 Sep 2028

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$32,000.00

COE Rebate Amount: \$20,774.00

Total Rebate Amount: \$34,182.00

The information contained herein is correct as at 26 Apr 2021

OK

Skoda Octavia 1.0A TSI Ambition

- Overview
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

Das WeltAuto.
Used cars you can trust. Guaranteed.

Price	\$72,988		
Depreciation ?	\$8,920 /yr View models with similar depre	Reg Date	29-Jun-2018 (7yrs 2mths 2days COE left)
Mileage	57,000 km (20.2k /yr)	Manufactured ?	2018
Road Tax ?	\$392 /yr	Transmission	Auto
Dereg Value ?	\$37,879 as of today (change)	OMV ?	\$17,878
COE ?	\$34,400	ARF ?	\$17,878
Engine Cap	999 cc	Power	85.0 kW (113 bhp)
Curb Weight ?	1,414 kg	No. of Owners ?	1
Type of Vehicle	Mid-Sized Sedan		

Features
Octavia 1.0, 115 BHP Turbocharged TSI Engine, 200 Nm Torque, 7 Speed DSG, 7 Airbags. View specs of the SKODA Octavia (2018-2021)

Accessories
8 Inch 'Bolero' Infotainment System, Smartlink, PDC With Rear View Camera, KESSY, Cruise Control, Electrical Retractable Side Mirrors.

Description
Singapore's Only Certified Volkswagen/Skoda Pre-Owned Centre, 115 Points Check By Skoda Singapore, Certified Vehicle History And Mileage, No Chassis/Structural Damage. Warranty Till June 2023.Call For A Viewing Appointment Before It's Gone!


Category
PARF Car, Premium Ad Car

Status
Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources

sgcarmart Used Car Warranty
Compare Ask your dealer for a warranty on this car. Learn more

https://www.sgcarmart.com/used_cars/info.php?ID=982766&DL=3103



- Shortlist
- Compare
- Report Error
- More

Seller Information

Das WeltAuto
★ PREMIUM DEALER 2021 ★
33 vehicles for sale. 43 sold in past 3 months

24 Leng Kee Road #05-02A
Leng Kee Autopoint
Tel: 64966488
Search cars nearby

Agnes See	96202800
Zac Neo	88227799
Benjamin Lim	91770312
Lim Kok Heng	84850288