



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHEN XINYOU			Ref: CC4/ASM21004945/Kgs3q2 Date: 07/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBC 8222J	Veh. Inspected	SJA 3833U
	Policy No.	GA053720	Coverage (\$)	0.00
	Claim No.	S1M038BL	Excess (\$)	0.00
	Assign From		Assign Date	20/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PICNIC (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JTEGH23B200022805	Colour	METALLIC BLUE
	Odometer	191565 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	PETLAS	9 mm
	L/H Front Tyre	205/60 R16	PETLAS	9 mm
	R/H Rear Tyre	205/60 R16	PETLAS	9 mm
	L/H Rear Tyre	205/60 R16	PETLAS	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY & UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/04/2021	Inspection Date	20/04/2021
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	