



Co. Reg. No.: 201416720C  
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
 Tel : 6636 9100 Fax : 6636 9113

Date : 19/04/2021

Jaslin.

TO: China Taiping Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

Our Customer : Jang Hu Lang  
 Vehicle No : SJG6848B  
 Model : Toyota Lexus ES250 4DR Sedan  
 Manufacture Year : 2019  
 Date of Accident : 17/04/2021  
 Total Estimate Repair Days : 5  
 Total Pages : 1

Attn : Motor Claims Department  
 Fax : 6224 7478

Re: Repair Estimate For Third Party Claim against GBF7721B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Front bumper <i>del</i>	1	\$1,135.00	\$1,135.00	✓
2	Front bumper side retainer RH <i>del</i>	1	\$54.00	\$54.00	f
3	Front sensor RH <i>del</i>	1	\$488.00	\$488.00	312
4	Headlamp RH <i>del</i>	1	\$3,753.00	\$3,753.00	✓
5	Fog lamp garnish w/chrome RH <i>del</i>	1	\$252.00	\$252.00	x
6	Front fender RH <i>del</i>	1	\$1,617.00	\$1,617.00	x
7	Front sports rim RH <i>del</i>	1			x
			<b>Total</b>	<b>\$7,299.00</b>	
			<b>Less 10%</b>	<b>\$729.90</b>	
			<b>Sub Total 1</b>	<b>\$6,569.10</b>	
<b>B.</b>	<b>Spare Parts (S/Nett)</b>				
1	Front bumper clip <i>del</i>	10	\$5.00	\$50.00	30
			<b>Sub Total 2</b>	<b>\$50.00</b>	
<b>C.</b>	<b>Labour</b>				
1	To check wiring and refocus headlamp.			\$50.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	250
3	Spray painting all affected parts & areas.			\$600.00	250
			<b>Total Labour</b>	<b>\$1,050.00</b>	
			<b>Total Repair Cost</b>	<b>\$7,669.10</b>	

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Surveyor's Details	
Name	Adrian L
Contact	96893735
Survey Date	21/04/21
Recommender	Authorize / Not Authorize
Before Paint	Yes No

03 days.

total: 5240  
 CP/P