



Claim	S1M038D3
Reference	CS3/ASM21004960/Gqce2 
Loss Date	17 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	20 Apr 2021 8:30:00 AM
Request Date	20 April 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SMU6717L
Vehicle	
Registration #	
Make	TPVD MERCEDES BENZ
Model	B200

Service Address

’ ’ ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2103134.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	5 May 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	5 May 2021

FAQ

English (SG) ▾

Elaine Kuan ▾

SUBTYPE

AUTHOR

DATE
UPLOADED

Home

Service Requests

...

ence

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)

5 May
2021

SMU6717L Preliminary
advice.pdf.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS
PTE LTD (TP)

27 April
2021

SMU6717L Resurvey Photo.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)

27 April
2021

SMU6717L Inspection
Photo.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)

27 April
2021

EMAIL FROM SOLICITOR FOR TP
REG.msg.msg

Letters and
Correspondence

Others

NIKAM Santosh Pandurang

20 April
2021

SHA2606P insd gia.pdf.pdf

Reports & Statement

GIA Report

NIKAM Santosh Pandurang

20 April
2021

SJ04214J000C-SHA2606P.pdf.pdf

Reports & Statement

Accident statement

ILHAM Luqman Hakim

19 April
2021