

AIR DETAILS

ference

Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2021)
ts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
our:	Repairer's	(Price-denominated Standard List)
nt Code:	ComfortDelGro Engineering Pte Ltd/SHD3328U/20/04/2021 08:46	
lidity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
urther Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*DOOR SIDE MIRROR LH	20.00	0.00	Rp *670.00 FL
1		*FRONT DOOR LH	20.00	0.00	Rp *2,256.40 FL
1		*FRONT FENDER LH	20.00	0.00	Rp *663.00 FL
1		*FRONT DOOR COMFORTDELGRO LOGO LH	0.00	0.00	ent / *75.00 F

anchise part. L=ListItemDisc.

Sub Total (S\$)	3,664.40
- List Item Discount on L Items (S\$)	717.88
Total Parts (S\$)	2,946.52

ComfortDelGro Engineering Pte Ltd/SHD3328U/20/04/2021 08:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

9N 75

Repairer Estimates

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 700.00
2	SPRAY PAINTING CHARGE	New	600 700.00
3	TRANSFER OF DOOR	New	mm. X 120.00
Gross Labour Cost (S\$)			950 1,520.00

ComfortDelGro Engineering Pte Ltd/SHD3328U/20/04/2021 08:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495449
'up' 20/4/21 @ 3pm
4/5 Resury after repair
tanpin e/khanto.com
2 days

\$1036 #
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: