

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHD4070E/20/04/2021 09:31	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR LH	20.00	0.00	*1,789.90 FL
2	1		*FRT DOOR LOWER PROTECTOR LH	20.00	0.00	*125.30 FL
3	1		*ROCKER PANEL GARNISH LH	20.00	0.00	*290.00 FL
4	1		*FRT DOOR COMFORTDELGRO LH	0.00	0.00	*75.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,280.20
- List Item Discount on L Items (\$\$)	441.04
Total Parts (\$\$)	1,839.16

ComfortDelGro Engineering Pte Ltd/SHD4070E/20/04/2021 09:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2205.20
20% - 1764.16
4W 75

TS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350. 400.00
2	SPRAY PAINTING	New	375 600.00
3	TUFF KOTE	New	30 50.00
Gross Labour Cost (S\$)			755 1,050.00

ComfortDelGro Engineering Pte Ltd/SHD4070E/20/04/2021 09:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

\$ 2605.16
2 days

Tanphn 974 15749
WP' 20/4/2021 3pm
2 days
P/P Resurvey before paint
Tanphn e/ikawto-wr

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: