SG0G214M0001 / Go Ahead Singapore Pte Ltd ENTRY DATE & TIME: 26/04/2021 09:52 (SGT) SUBMITTED BY: Chan Weijie VERSION: 1 (26/04/2021 09:52 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving the control of this report will fee fee be made qualified to the proposition by interested parties. and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDEN'	T STATEMENT
Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	26/04/2021 09:52 (SGT) 18/04/2021 19:27 (SGT) Near 213 Punggol Walk, Singapore 820213 - Singapore
DETAILS OF	FOWN VEHICLE
Vehicle Registration Number	SG5070C
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes GO AHEAD SINGAPORE PTE LTD  (Phone) +65- (Office) +65-
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC	Volvo B9tl - Employment No - Claiming third party Bus Auto 9400
INSURANCE COMPANY	
Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number	MS First Capital Insurance Ltd Comprehensive Yes
DDIVED.	

Lo Meng Hin

Name of Driver


Work Permit No

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver	Outdoor 6 YEARS AND 9 MONTHS Male (Phone) +65
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?  Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other material or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 1
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Police Station Name Police Station Phone No Alt. Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?	Yes Pasir Ris Neighbourhood Police Centre (Phone) +65-18005852999 (Fax) +65-65855261 1 Pasir Ris Drive 4 #01-01 Singapore 519457 No
CIRCUMSTANCES OF ACCIDENT	
WHILST TRAVELLING TOWARDS 75159 • BLK 874 VIA THE LEF HATCHBACK [SMX2350X] THAT WAS TRAVELLING AHEAD STO UNABLE TO STOP IN TIME TO AVOID A REAR-END COLLISION	OPPED ABRUPTLY FOR NO PARTICULAR REASON. I WAS
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Was there any audio recorded?	Yes Yes DIFFERENT FORMAT No

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration NumberSMX2350XVehicle ManufacturerToyotaVehicle ModelPrius

Vehicle Variant	_
Vehicle Colour	White
Vehicle Category	Private hire
Name of Driver	ONG CHWEE SENG
NRIC No	
Contact Number	-
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-











Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Report No.	T/20210419/2153

1 of 4

	ne Report M 21 22:11	fade:	Vide Report No.:	Station Diary No.: 133
Informa	nt's Partici	ulars		CENTER SEAL AND THE SEARCH OF THE
Name of	Informant:		Address:	
LO MEN	G HIN			
ID Type			Contact No.: Home/Office:	Mobile
Nationali MALAYS	O		Email:	
Sex: Male	Age: 28	Date of Birth:	Type of Informant: Driver	
Race: Chinese	1,0		Language:	Institution / School Name:
Occupation: Bus Driver			Driving Licence Information: Class:	Date of Expiry:

General Infor	mation of the Accide	ent			
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 18/04/2021 19:30	Type of Location: Straight Road	
Location: PUNGGOL R Weather: Clear	ROAD	Road Surface: Wet		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collis	sion: ving Vehicles - Head <sup>*</sup>	To Rear		Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SG5070C	Bus/Coach/Mi nibus	VOLVO	B9TL 9.4L AUTO TURBO ABS	Multi-Colored	Slightly Damaged	20
SMX2350X	Car	TOYOTA	PRIUS 5DR HATCHBAC K (AUTO)	Silver	Slightly Damaged	4

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20210419/2153

2 of 4 Report No. T/20210419/2153

Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457

Tel No: 1800-5852999

#### CONTINUATION OF REPORT

Driver				ENS.		
Name	LO MENG HIN			ID No		
Related Vehicle	SG5070C (Bus/Coa	ch/Minibus	)	Conta	ct No.	
Hospital/Clinic	NIL		Class Drivin Licene Expiry	g	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL Date Disc			harge	NIL	
No. of Days granted Medical Leave NIL		Degree of				
Driver						
Name	ONG CHWEE SENG		ID No			
Related Vehicle	SMX2350X (Car)		Conta	ct No.		
Hospital/Clinic	NIL		Class Drivin Licend Expiry	g	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL Date Disc			harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	fInjury	NIL	

### Brief Details.

On 18/04/2021 at around 7.30 pm, I was driving Go Ahead Bus service no.118 and I was heading towards Changi business park. As I was driving along Punggol road on the extreme left lane, there was another vehicle in front of me. As such, I kept a safety distance from the vehicle as it was a down slope. Over along Punggol road, there was a chevron/divider in between the 3rd lane and 2nd as the 2nd and 1st lane is the entrance into TPE.

During that point in time, I saw the said vehicle singled right. However, he suddenly applied brake after he drove past the chevron/divider. As I was unable to brake in time, the front of my bus collided into the rear of the said vehicle. There were about 20 passengers on board my bus and 4 passengers with the said vehicle. However, no one was injured.

Both me and the driver then alighted and exchanged particulars. Upon asking, the driver told me that he intended to make a lane change and wanted to enter TPE. This is why he signaled right. However, he did a sudden brake when he realized that was unable to enter the lane as he had already driven pass the chevron/divider.

Initially, he wanted to do a private settlement but since I am driving a company bus, I rejected his offer.

I have CCTV installed in my bus as well.





Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457 Tel No: 1800-5852999 3 of 4 Report No. T/20210419/2153

CONTINUATION OF REPORT