

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GS1 Reg. No. 19-900/198-8					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	i	Ref:	CS/AGI21005004/Kvf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	ו	Date:	28/05/2021	
			(	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLC 6686Z	Veh. Inspected		SMV 4089Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009906/ST	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		21/04/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH (A)	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	ZWR800428408	Colour		METALLIC BLACK	
	Odometer	38204 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	GOODYEAR		8 mm	
	L/H Front Tyre	225/45 R17	GOODYEAR		8 mm	
	R/H Rear Tyre	225/45 R17	GOODYEAR		8 mm	
	L/H Rear Tyre	225/45 R17	GOODYEAR		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/04/2021	Inspection Date	!	03/05/2021	
	Survey held at	at LIM YEW BOO SPRAY PAINT CO				
		BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: