

(08/11/13) wef

ASS. REC. BY: Pearl

REF:

CS/CT121005023/Rv43

221M

COB XPRM: 2022/04

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: WC 1508Hat Workshop m/s. WOODLANDS TRANSPORTof B, GUL CIRCLEInsured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 16K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: WC 1508HYr Regn: 2007 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer orMake: ISUZU C4H 52Sc.c 15681Colour MULTI

A/C: Insured / Std / NI / NA

Sp. Reading 372011

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALUYH557000059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R225R: 22" D/P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FRONWAY

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 16/04/21D.O.I. 26/04/21Survey held at WOODLANDS TRANSPORT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 9K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS, SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 19/04/21 **9893 7093**
 VEHICLE NO: WC1508H
 DRIVER: THIRUMAL JEGATHEESH
 ATTENTION TO:
 PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
 Q REF No: Q21/04/1207
 DEPARTMENT: WTS Mixer Truck Department
 ACCIDENT DATE: 16/04/21
 REF No: JW-0421-180

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	STAY MIRROR SIDE <i>new 67</i>	1	426.6	426.60
2	MIRROR ASM UNDER LHS <i>MIS</i>	1	101.4	101.40
Labour Costs				
1	TO DISMANTLE DAMAGED PARTS AND INSTALL FRONT LHS MIRROR STAY AND MIRROR.	1	120	<i>100</i> 120.00
TOTAL:				648.00
Total Amount				SGD 648.00

Remarks:

[Signature] 19/4/21
 Signature of Workshop Dpt

[Signature] 19/4/21
 Signature of Department Head

Signature of Claim Department

Ram

hp 90010068

1 days

26/04/21 @ 1130

11.30 am

Reg after repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/04/2021 14:22 (SGT)
Date of Accident 16/04/2021 10:15 (SGT)
Exact Location of Accident Singapore
Additional Location Information Upper Changi Road East
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number WC1508H

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Woodlands Transport Service Pte Ltd
Company Reg No 1XXXXX721M
Email Address GOO@WOODLANDSTRANSPORT.COM.SG
Mobile Phone No (Phone) +65-98383481
Alternative Phone No (Office) +65-65598954

VEHICLE PARTICULARS

Manufacturer Isuzu
Model CYH52S
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 15681

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number SD20V11551
Cover Note Number -

DRIVER

Name of Driver Thirumal Jegatheesh
Passport No/FIN GXXXX993X

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

10/07/1986
Outdoor
06/03/2018
3 YEARS AND 1 MONTH
Male
(Phone) +65-98937093
-
GOO@WOODLANDSTRANSPORT.COM.SG
8 GUL CIRCLE
-
629564
No
Employee
No
-
-

IMPORTANT NOTICE
1. Please report correctly the
2. This form must be
3. Ind

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Hit and run / Vandalism / Damaged whilst parked
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
No
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Nanyang Neighbourhood Police Centre
(Phone) +65-18007929999
(Fax) +65-67912972
No. 2 Jurong West Avenue 5 Singapore 649482
No
-

CIRCUMSTANCES OF ACCIDENT

On 16/4/2021, at about 10:15 hrs, my vehicle was along the traffic junction of Upper Changi Road East in lane 1. The weather was clear with dry road surfaces. As the traffic light turn green, I proceeded to moved forward. However, a vehicle, YN5790A, that was traveling on my left, grazed against my truck. Subsequently, I horned but the said vehicle did not stopped. As a result, my truck sustained damages on the LH mirror mounting. No one was injured in the accident.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

UPPER CHANGI ROAD EAST

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

I/We declare the foregoing particulars are true in every respect.

GLAMC SketchPlatform_V3

7. ~~1/2~~ 1/2

Wan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	721M
Vehicle No.:	WC1508H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Apr 2021
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	6WG1406620
Chassis No.:	JALCYH52S77000059
Maximum Power Output:	-
Open Market Value:	\$113,869.00
Original Registration Date:	09 Nov 2007
First Registration Date:	09 Nov 2007
Transfer Count:	0
Actual ARF Paid:	\$0.00

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	31 Oct 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$21,477.00
COE Rebate Amount:	\$6,489.00
Total Rebate Amount:	\$6,489.00

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 27 Apr 2021

OK

Isuzu CYH52S (COE till 08/2022)

Overview Financial Accessories Similar Research Photos Map

Price	\$14,800	Lifespan	02-Sep-2027
Depreciation ?	\$11,000 /yr	Reg Date	03-Sep-2007 (1yr 4mths 4days COE left)
Mileage	N.A.	Manufactured ?	2007
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$4,821 as of today (change)	OMV ?	\$109,384
COE ?	\$17,920	No. of Owners ?	1
Engine Cap	15,681 cc		
Curb Weight ?	13,900 kg		
Type of Vehicle	Truck		

Features

20.1Ton Payload Concrete Mixer/Cement Mixer.

Description

In House Loan Available, Can Extend Another 5 Years COE. Well Kept. Call Now For More Info.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist



Compare



Re



More

Seller Information

Thiam Heng Motor

13 vehicles for sale, 21 sold in past 3 mths

1 Bukit Batok Crescent #03-17/18

WCEGA Plaza

Tel: 64695691

Search cars nearby



Johnny Yeo

9855815

Chuan

8183393

Anthony Toh

9681928

Posted on: 23-Feb-2021 | Last Updated on: 23-Feb-2021

Upfront Payment

> more Financial info

Transfer Fee ?

\$25

Down Payment ?

\$1,480 (change) Maximum 90% Loan

1st Instalment

SHORTLISTED

HISTORY

Compare



\$877 Based on 2.48% Interest rate

Get your loan approved now in 60 seconds. T&Cs apply.
Learn More

