

|   |   |   |        |   |   |   |   |      |   |   |   |   |             |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ▼ | 📄 | ✓ | 🖨 | Find   Next |
|---|---|---|--------|---|---|---|---|------|---|---|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                                  |                          |                |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|--------------------------|----------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                                                  |                          |                |  |
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                     |                                                                                                  | Ref: CS/AIG21005027/Kvf3 |                |  |
| 78 SHENTON WAY #09-16                                                                                                                  |                                                                                                  | Date: 22/04/2021         |                |  |
| AIG BUILDING                                                                                                                           |                                                                                                  |                          |                |  |
| SINGAPORE 079120                                                                                                                       |                                                                                                  | Code: AIG                |                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                  |                          |                |  |
| <b>Insured Veh.</b>                                                                                                                    | SKD 4193Z                                                                                        | <b>Veh. Inspected</b>    | SLH 7080M      |  |
| <b>Policy No.</b>                                                                                                                      |                                                                                                  | <b>Coverage (\$)</b>     | 0.00           |  |
| <b>Claim No.</b>                                                                                                                       |                                                                                                  | <b>Excess (\$)</b>       | 0.00           |  |
| <b>Assign From</b>                                                                                                                     | DIVYASHNI SUBRAMANIAM                                                                            | <b>Assign Date</b>       | 22/04/2021     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                  |                          |                |  |
| <b>Make &amp; Model</b>                                                                                                                |                                                                                                  | <b>c.c</b>               | 0              |  |
| <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                                           | <b>Year of Reg.</b>      |                |  |
| <b>Chassis No.</b>                                                                                                                     |                                                                                                  | <b>Colour</b>            |                |  |
| <b>Odometer</b>                                                                                                                        | -                                                                                                | <b>Steering</b>          |                |  |
| <b>Brakes</b>                                                                                                                          |                                                                                                  | <b>Modification</b>      |                |  |
| <b>General</b>                                                                                                                         |                                                                                                  |                          |                |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                  |                          |                |  |
|                                                                                                                                        | <b>Size</b>                                                                                      | <b>Make</b>              | <b>Balance</b> |  |
| <b>R/H Front Tyre</b>                                                                                                                  |                                                                                                  |                          | mm             |  |
| <b>L/H Front Tyre</b>                                                                                                                  |                                                                                                  |                          | mm             |  |
| <b>R/H Rear Tyre</b>                                                                                                                   |                                                                                                  |                          | mm             |  |
| <b>L/H Rear Tyre</b>                                                                                                                   |                                                                                                  |                          | mm             |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                  |                          |                |  |
|                                                                                                                                        |                                                                                                  |                          |                |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                  |                          |                |  |
| <b>Accident Date</b>                                                                                                                   | 02/02/2021                                                                                       | <b>Inspection Date</b>   | 22/04/2021     |  |
| <b>Survey held at</b>                                                                                                                  | S THREE AUTOMOTIVE & RECOVERY PTE LTD<br>BLK 8 SIN MING IND EST<br>#01-64/66<br>SINGAPORE 575643 |                          |                |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                  |                          |                |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                  |                          |                |  |