

20/11/13) waf

ASS. REC. BY: P. Jones

REF:

CS/CTI 21005029/RH3

386H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 20932at Workshop m/s: VOLKSWAGENof 2471, ALEXANDRA RDInsured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 67K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ 20932 Yr Regn: 2016 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VOLKSWAGEN CADDY MAXI 1.4 c.c. 1395Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 102584 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV 22222KZX047637Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/04/21 D.O.I. 23/04/21Survey held at VOLKSWAGEN

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FRONT N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 20K

Finalised amount of \$ 13,517.15 / 7 days of repair is confirmed

red:5815.80;30%

19332.951

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS, \$ _____

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
Koh
Min-Dao, Caleb
31 HINDHEDE WALK
#05-02
SINGAPORE 587967

Document no.
Document date 21-04-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021015299/ 1
Job order date 21-04-2021
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SLJ2093Z	SAJHK5	30-11-2016	WV2ZZZ2KZHX047637	Caddy Maxi wvHigh 92 TSI A7 1.4	91,988

REPAIR LIMIT: \$

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
2K5827025B	Rear Trunk Lid With Window d 169300m2	1	pcs.	2,945.74	#1	2,945.74	3,151.94
D 169300M2	1k Window Adhesive	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer	1	pcs.	27.39	#1	27.39	29.31
D 00950025	Applicator	2	pcs.	10.12	#1	20.24	21.66
D 181802M1	Activator For Precoated W	1	pcs.	25.14	#1	25.14	26.90
2K0829193AA	Gasket BOOT WETHERSTRIP	1	pcs.	143.88	#1	143.88	153.95
N 90479203	Riveted Cap Nut	4	pcs.	2.23	#1	8.92	9.54
2K5945087J	Additional Brake Light W 3RD BRAKELIGHT	1	pcs.	173.26	#1	173.26	185.39
2K5853079	Decorative Moulding BOOT LID LOWER MLDG CHROM	1	pcs.	283.14	#1	283.14	302.96
7E0853630D DPJ	Vw Sign Black/Bright Chro	1	pcs.	91.06	#1	91.06	97.43
2K5853687 739	Inscription Chrome NAME PLATE - CADDY	1	pcs.	64.70	#1	64.70	69.23
5G0853675A JZQ	Inscription Chrome Shine NAME PLATE - TSI	1	pcs.	81.92	#1	81.92	87.65
2K5827505E	Hood Latch BOOT LID LOCK	1	pcs.	88.48	#1	88.48	94.67
8D5827713A	Plug	2	pcs.	2.43	#1	4.86	5.20
2K5807417A GRU	Cover For Bumper Primed REAR BUMPER	1	pcs.	884.66	#1	884.66	946.59
2K5807305B	Bumper REINFORCEMENT	1	pcs.	574.15	#1	574.15	614.34
2K5807393A	Guide Piece BUMPER SIDE BRACKET LH	1	pcs.	27.98	#1	27.98	29.94
2K5807394A	Guide Piece BUMPER SIDE BRACKET RH	1	pcs.	27.98	#1	27.98	29.94
N 0385501	Rivet	10	pcs.	0.48	#1	4.80	5.14
357853586B	Grommet	10	pcs.	1.56	#1	15.60	16.69
2K5998491	Repair Kit For Sensor SENSOR BRACKET	1	pcs.	52.75	#1	52.75	56.44
5Q0919275B GRU	Sensor Primed	3	pcs.	164.62	#1	493.86	528.43
2K5971883	Cap For Sensor	3	pcs.	4.86	#1	14.58	15.60
5Q0919133 9B9	Seal Ring Satin Black	3	pcs.	1.28	#1	3.84	4.11
2K5971541M	Harness For Bumper SENSOR WIRE HARNESS	1	pcs.	178.73	#1	178.73	191.24
2K2945095N	Taillight LH	1	pcs.	259.13	#1	259.13	277.27
WHT008867	Ballpin	2	pcs.	3.11	#1	6.22	6.66

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
Koh
Min-Dao, Caleb
31 HINDHEDE WALK
#05-02
SINGAPORE 587967

Document no.
Document date 21-04-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021015299/ 1
Job order date 21-04-2021
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SLJ2093Z	SAJHK5	30-11-2016	WV2ZZZ2KZXH047637	Caddy Maxi vvHigh 92 TSI A7	91,988

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
2K5945105D	Reflector <i>hcm</i> LH	1	pcs.	53.02	#1	53.02	56.73
2K0813307	Rear Apron <i>3?</i> REAR END PANEL	1	pcs.	272.73	#1	272.73	291.82
D 007500A2	Zinc Spray <i>?</i>	1	pcs.	67.34	#1	67.34	72.05
D 180003M2	2k-Body Adhesive <i>?</i>	1	pcs.	428.72	#1	428.72	458.73
D 476KD1M2	Sealant Can Be Sprayed <i>?</i>	1	pcs.	64.15	#1	64.15	68.64
	LABOUR	6	pcs.	840.00	#1 <i>1680</i>	5,040.00	5,392.80
	SPRAY PAINT	5	pcs.	800.00	#1 <i>1600</i>	4,000.00	4,280.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1 <i>420</i>	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50

Quotation valid till 28-04-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	18,455.22	7%	1,345.07	19,215.22	20,560.29
Total	760.00	18,455.22		1,345.07	19,215.22	20,560.29

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg for online services (appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARM
Hp 90010068
6 days
23/04/21 @ 1150
Resy before part

AXA (NOT INHOUSE)

VS

CHINA TAIPING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/04/2021 09:05 (SGT)
Date of Accident 20/04/2021 17:19 (SGT)
Exact Location of Accident Singapore
Additional Location Information bukit timah road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ2093Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner KOH MIN-DAO CALEB
NRIC No SXXXX356H
Email Address calebkoh@gmail.com
Mobile Phone No (Phone) +65-98004255
Alternative Phone No (Home) +65-98004255

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Caddy
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1400

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number GA519761/1
Cover Note Number -

DRIVER

Name of Driver GOH SUI LIN
NRIC No SXXXX164C

Date Of Birth 05/11/1997
 Occupation Indoor
 Date Of Driving Pass 01/12/1998
 Driving experience 22 YEARS AND 4 MONTHS
 Gender Female
 Mobile Number (Phone) +65-93856124
 Alt. Phone Number -
 Email Address gohsuilin@yahoo.com.sg
 Address 216B BOON LAY AVE #14-207
 Address complement -
 Postcode 642216
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Spouse
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

refer to sketch plan


ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? ~~No~~ Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMS165D
 Vehicle Manufacturer Mercedes
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver YONG HWEE
 Contact Number (Phone) +65-90462086
 Address -
 Address complement -

Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


My car has come to a stop at a ^{queue for a} U-turn along Bukit Timah Road just after Hua Chong Institution. The Mercedes hit my car from the back.

SMS 165 D


Driver of SMS 165D - Yong Hwee
9046 2086

DECLARATION


I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:
21/4/2021
830 AM


Driver's Signature
(If driver is not the policyholder)

Date & Time: 21/4/2021
830 AM


Reporting Centre Personnel's Signature

Name:
NRIC/FIN No: 21 APR 2021

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

21/4/2021
830 AM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

21/4/2021
830 AM

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

21 APR 2021

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices!
Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

31 Oct 2018 Toyota Vios 1.5A E \$67,800



Low Monthly Instalment! Low Depreciation! Next Servicing At 45,000KM! Value 4
Art Automobiles Pte Ltd StarAd



Browse by Category

Sort by Date Posted

20 results/page

Advanced Search

2 vehicles

volkswagen caddy maxi

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

volkswagen caddy maxi

Any

Any

2017

Any

Any

Any

Available



Volkswagen Caddy MPC Maxi 1.4A TSI

\$68,800

\$9,900 /yr

31-Jan-2017

1,395 cc

-

MPV

Available

SLK8x75 Carplate. 7 Seater MPV Passenger Car, Van Alike. Good For GRAB & Delivery. Selling Cheap. Low Depreciation. Fully Service By Volkswagen Agent, Service Record Available. Well Kept. Good Condition. High Trade-In. Bank Loan/In House Loan Available. Owner Con...

Posted: 22-Apr-2021 Tags: 2017 Volkswagen Caddy, Volkswagen Caddy, Volkswagen, Caddy



Volkswagen Caddy Maxi 2.0A TDI

\$61,800

\$9,350 /yr

30-Nov-2017

1,968 cc

63,965 km

Van

Available

Fuel Type: Diesel

5 Years Agent Warranty! Fully Maintained By Agent - Volkswagen! Vehicle Just Did A Full Check, Servicing By Agent Recently. Guaranteed In Top Notch Condition, Flawless Unit. Look Like Brand New Unit. Extremely Rare Auto Diesel Caddy Maxi Van, Smooth And Reliable Engi...

Car (S) Pte Ltd

Posted: 31-Mar-2021 Tags: 2017 Volkswagen Caddy, Volkswagen Caddy, Volkswagen, Caddy

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view **Expired ads**

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Rental Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used volkswagen caddy maxi, volkswagen caddy maxi Singapore, used volkswagen caddy maxi Singapore, used volkswagen caddy maxi, used vehicles Singapore or even buy used volkswagen caddy maxi Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2021 sgCarMart, Singapore. All rights reserved.

Back to OneMotoring

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	356H
Vehicle Details	
Vehicle No.:	
Vehicle to be Exported:	SLJ2093Z
Intended Deregistration Date:	Yes
Vehicle Make:	22 Apr 2021
Vehicle Model:	VOLKSWAGEN
Primary Colour:	CADDY MAXI 1.4 TSI AT SAJHK5
Manufacturing Year:	Grey
Engine No.:	2016
Chassis No.:	CZC635290
Maximum Power Output:	WV2ZZZ2KZHX047637
Open Market Value:	92.0 kW (123 bhp)
Original Registration Date:	\$25,822.00
First Registration Date:	30 Nov 2016
Transfer Count:	30 Nov 2016
Actual ARF Paid:	1
Intended PARF Rebate Details	\$23,151.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2026
PARF Rebate Amount:	\$17,363.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$29,508.00
Total Rebate Amount:	\$46,871.00

The information contained herein is correct as at 22 Apr 2021

OK