

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/SMO21005031/Ugf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMY9063

at Workshop m/s

of

Insured:

Policy No.

Claims No. CMTD2101271/RUC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$11800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 12 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMY9063

Yr Regn:

22/8/07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Toyota corolla AXIO c.c 1496

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

211/88

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NZE1416039749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70 R 14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

21/4/21

D.O.I.

22/4/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s & Rear w/screens cracked

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

see unit / 21-8-2022 LTA 5992 Nett \$5808

26/4/2021 Informed Ruth we are pending estimate from repairer.

3/5/2021 L/S \$5500 confirmed with Shawn.

(RED \$18033.66; 77%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 7/5 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : TP

Lump Sum / ~~TP~~ (\$ 5500

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 728C

Vehicle Details

Vehicle No.: SMY906B
Vehicle to be Exported: No
Intended Deregistration Date: 26 Apr 2021
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5 A
Primary Colour: Grey
Manufacturing Year: 2007
Engine No.: 1NZC648693
Chassis No.: NZE1416039749
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$12,590.00
Original Registration Date: 22 Aug 2007
First Registration Date: 22 Aug 2007
Transfer Count: 3
Actual ARF Paid: \$13,849.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Aug 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$22,700.00
COE Rebate Amount: \$5,992.00
Total Rebate Amount: \$5,992.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Apr 2021

OK