

Service Request Details

Claim	S1M037QY
Reference	CS3/ASM21005038/Gqce2 
Loss Date	10 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	12 Apr 2021 3:30:24 PM
Request Date	21 April 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	FBE6396T
Vehicle	
Registration #	
Make	TPVD Yamaha
Model	RXZ

Service Address

'''

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

YU Dominic Yishan

dominic.yuys@axa.com.sg

Additional Instructions

Messages1 Invoices History **Documents** Assessment Metrics Notes

Document Type

Document SubType

 Upload Documents

Already Attached

NAME	DATE UPLOADED			
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2103068.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 April 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	30 April 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	30 April 2021
 FBE6396T Inspection Photo_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2021
 AXA Immediate Advice - FBE6396T (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2021
 AXA Immediate Advice - FBE6396T (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2021
 SHD7116M INSD GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	21 April 2021
 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	21 April 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SHD7116M INS GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	12 April 2021
 SJ04214B000E-SHD7116M.pdf.pdf	Reports & Statement	Accident statement	ILHAM Luqman Hakim	12 April 2021